

Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK

Report ID: MAXIA20250509102337 Test Time: 2025-05-09 10:23:37 Technician: Sbu

Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mercedes-Benz/204.003 - C 250 CDI BlueEFFICIENCY Sedan, C Odometer Reading: 128787km

250 CDI Sedan/--

VIN: WDD2040032R189390 License Plate: HT29KVGP

Customer Information

Name: Dekra MFC AUCTION HOUSE Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01514

Version: V19.07 Repair Order Number: --

System Scanned(37)	
System	Status/DTC
ECM(Engine Control Unit)	Q 1
TCM(Transmission Control Unit)	Q 1
ESP(Electronically controlled vehicle stability braking system control unit)	O
SRS(Supplemental Restraint System Control Unit)	Q 10
KI(Instrument Cluster)	Q 1
PTS(Parking System)	Q 8
SAMF(Front SAM signal acquisition control unit)	Q 8
LIN:AISP(Interior mirror)	② 0
LIN:FSW(Wiper Motor)	Q 8
LIN:GTO(Garage Door Opener)	Q 4
LIN:OBF(Upper Control Panel)	② 0
LIN:VCS(Rain/sunlight sensor)	② 0
SAMR(Rear SAM signal acquisition control unit)	Q 8
LIN:BSN(Battery Sensor)	② 0
LIN:EDW(Interior Protection System Control Unit)	② 0
EZS(Electronic Ignition Lock Control Unit)	Q 1
KLA(Air Conditioner Control Unit)	② 0
HU(Head Unit Control Unit)	Q 2

MaxiSys MS906 BT

Page 1

/Mercedes-Benz/204.003 - C 250 CDI Tes BlueEFFICIENCY Sedan, C 250 CDI Sedan	t Time: 2025-05-09 10:23:37 Report ID:	MAXIA20250509102337
DSI(Shift Lever Control Unit)		O
SW-SW-L(Left Headlamp Control Unit)	APAS	3
SW-SW(Headlamp Control Unit)	APAS	3
LIN:LAMSL(Left Front LED Lamp Unit Actuation Control Unit)	n	Q 3
LIN:LAMSR(Right Front LED Lamp Unit Actuat Control Unit)	ion APAS	Q 3
DMFL(Left Front Door Control Unit)		Q 2
DMFR(Right Front Door Control Unit)		Q 2
DMRR(Right Rear Door Control Unit)		Q 2
DMRL(Left Rear Door Control Unit)		Q 2
ZBE(Head Unit Display)		Q 2
ZAN(Center Display Control Unit)		3
UCI(Media Interface)		3 1
RBTMFR(Right Front Seat Belt Tensioner Cont Unit)	:rol	Q 4
RBTMFL(Left Front Seat Belt Tensioner Contro	ol Unit)	3
MRM(Steering Column Control Unit)		③ 1
MFK(Multifunction Camera)	APAS	3
FSCU(Fuel Pump Control Unit)		② 0
DBE(Sunroof Control Unit)		Q 2
CGW(Central Gateway Control Unit)		3 1
₼ DTC (92)		
ECM(Engine Control Unit) (1 DTC)		
DTC Description	Status	

DTC	Description	Status
P068500	The output for relay 'Circuit 87' has an electrical fault or an open circuit.	Stored
TCM(Transmission Control Unit) (1 DTC)		
DTC	Description	Status
P1636	'CP48 (Fully integrated transmission control control unit)' is defective.	Stored

MaxiSys MS906 BT

Page 2

SRS(Supplemental Restraint System Control Unit) (10 DTCs)

× 11		
DTC	Description	Status
B007E13	The squib for emergency tensioning retractor 'Driver' has a malfunction. There is an open circuit.	Active and stored
B273513	The squib for pyrofuse 'On-board electrical network line' has a malfunction. There is an open circuit.	Active and stored
B275013	The squib for the sidebag 'Driver' has a malfunction. There is an open circuit.	Active and stored
B002913	Right windowbag/headbag squib fault - open circuit	Active and stored
B00E413	Right rear emergency tensioning retractor squib fault - open circuit	Active and stored
B00E313	Left rear emergency tensioning retractor squib fault - open circuit	Active and stored
B007F13	The squib for emergency tensioning retractor 'Front passenger' has a malfunction. There is an open circuit.	Active and stored
B009012	Left front crash sensor fault - open circuit or short circuit to positive	Active and stored
B009512	Right front crash sensor fault - open circuit or short circuit to positive	Active and stored
B210D00	The power supply is too low.	Stored(Event codes)
KI(Instrument C	cluster) (1 DTC)	

DTC	Description	Status	
U012187	Communication with ESP has a malfunction. The	Stored(Event codes)	
0012101	message is missing.	Stored(Event codes)	

PTS(Parking System) (8 DTCs)

r 13(raiking 3)	stein) (0 D 108)	
DTC	Description	Status
925D23	Outer right front distance sensor fault - no signal change: voltage level too low	Active and stored
925D4A	Outer right front distance sensor fault - wrong component installed	Stored
A10A00	The power supply in the system is too low.	Stored
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
925D24	Outer right front distance sensor fault - no signal change: voltage level too high	Stored
C44700	Implausible data were received from the central gateway.	Stored
C41500	Implausible data were received from 'ESP'.	Stored

www.autel.com MaxiSys MS906 BT Page 3

MAC	www.autel.con

B219116

MaxiSys MS906 BT

The power supply of circuit 30g is outside the valid range.

The limit value for electrical voltage has not been attained.

Stored

LIN:LAMSL(Left Front LED Lamp Unit Actuation Control Unit) (3 DTCs)

voltage limit value not reached



B284316

w.autel.com MaxiSys MS906 BT

Stored

	/204.003 - C 250 CDI Test Time: 2025-05-09 10:23:37 Sedan, C 250 CDI Sedan	Report ID: MAXIA2025050910233
DTC	Description	Status
B283F87	Right xenon bulb fault - missing message	Stored
B284216	Left light distribution servomotor fault - electrical voltage limit value not reached	Stored
B284316	Right light distribution servomotor fault - electrical voltage limit value not reached	Stored
LIN:LAMSR(Ri	ght Front LED Lamp Unit Actuation Control Unit) (3 DTCs)	
DTC	Description	Status
B283F87	Right xenon bulb fault - missing message	Stored
B284216	Left light distribution servomotor fault - electrical voltage limit value not reached	Stored
B284316	Right light distribution servomotor fault - electrical voltage limit value not reached	Stored
DMFL(Left Fro	nt Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)
A10A00	The power supply in the system is too low.	Stored(Event codes)
DMFR(Right Fi	ront Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
A10A00	The power supply in the system is too low.	Stored(Event codes)
DMRR(Right R	ear Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
A10A00	The power supply in the system is too low.	Stored(Event codes)
DMRL(Left Rea	ar Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
A10A00	The power supply in the system is too low.	Stored(Event codes)
ZBE(Head Unit	t Display) (2 DTCs)	
DTC	Description	Status
A10A00	The power supply in the system is too low.	Stored(Event codes)

Page 6

Www.autel.com MaxiSys MS906 BT

	z/204.003 - C 250 CDI Test Time: 2025-05-09 10:23:37	Report ID: MAXIA2025050910233
BlueEFFICIENCY	Sedan, C 250 CDI Sedan	
A10D00	The power supply is too low.	Stored(Event codes)
ZAN(Center Di	splay Control Unit) (3 DTCs)	
DTC	Description	Status
A10A	The power supply in the system is too low.	Stored(Event codes)
A10D	The power supply is too low.	Stored(Event codes)
C155	Communication with the instrument cluster has a malfunction.	Stored(Event codes)
UCI(Media Inte	erface) (1 DTC)	
DTC	Description	Status
A10D	The power supply is too low.	Stored(Event codes)
RBTMFR(Righ	t Front Seat Belt Tensioner Control Unit) (4 DTCs)	
DTC	Description	Status
510116	The supply voltage of 'CB72 (Right front reversible emergency tensioning retractor)' is too low (undervoltage).	Stored
510416	Emergency tensioning retractor function aborted due to excessively low supply voltage.	Stored
640300	Software error	Stored
510C08	The CAN message from 'CC52 (Electronic stability program control module)' is faulty.	Stored(Event codes)
RBTMFL(Left I	Front Seat Belt Tensioner Control Unit) (3 DTCs)	
DTC	Description	Status
510116	The supply voltage of 'CB71 (Left front reversible emergency tensioning retractor)' is too low (undervoltage).	Stored(Event codes)
510416	Emergency tensioning retractor function aborted due to excessively low supply voltage.	Stored(Event codes)
640300	Software error	Stored
MRM(Steering	Column Control Unit) (1 DTC)	
DTC	Description	Status
U11A300	Communication with 'Multifunction camera' has a malfunction.	Active and stored(Event codes)
MFK(Multifund	ction Camera) (3 DTCs)	
DTC	Description	Status
A3A813	The output for window heating has a malfunction. There is an open circuit.	Active and stored
A10D00	The power supply is too low.	Stored(Event codes)
A10A00	The power supply in the system is too low.	Stored(Event codes)

Page 7 www.autel.com MaxiSys MS906 BT

/Mercedes-Benz/204.003 - C 250 CDI	Test Time:	2025-05-09 10:23:37	Report ID:	MAXIA20250509102337
BlueEFFICIENCY Sedan, C 250 CDI Sedan				

DBE(Sunroof Control Unit) (2 DTCs)

DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)
A10A00	The power supply in the system is too low.	Stored(Event codes)

CGW(Central Gateway Control Unit) (1 DTC)

DTC	Description	Status
B210A00	The power supply in the system is too low.	Stored

Technician Notes 2016871497

Customer name:	
Technician:	
Date [.]	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



.autel.com MaxiSys MS906 BT
Page 8