

Shop: DEKRA MFC Tel: --Email: --Address: MFC Auction House Kempton Park

Report ID: MAXIA20231220161333 Test Time: 2023-12-20 16:13:33 Technician: Travino

Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

Vehicle Information	
/Mercedes-Benz/204.049 - C 180 BlueEFFICIENCY Sedan/	Odometer Reading: 228592km
VIN: WDD2040492R168166	License Plate: CY56973
Customer Information	
Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE	Tel: 0861033572
Device information	
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01482
Version: V18.80	Repair Order Number:

System Scanned(30)

System	Status/DTC
ECM(Engine Control Unit)	Q 9
TCM(Transmission Control Unit)	Q 1
ESP(Electronic Stability Program Braking System)	Q 2
SRS(Supplemental Restraint System Control Unit)	Q 1
KI(Instrument Cluster)	Q 3
PTS(Parking System)	9AS (8) 2
SAMF(Front Signal Acquisition Control Unit)	Q 6
LIN:ABF(Instrument Panel Switch)	O
LIN:AISP(Interior Rearview Mirror)	o
LIN:FSW(Wiper Motor)	O
LIN:OBF(Upper Control Panel)	O
LIN:VCS(Rain/Light Sensor)	O
SAMR(Rear Signal Acquisition Control Unit)	Q 9
LIN:BSN(Battery Sensor)	O
LIN:EDW(Interior Protection System Control Unit)	o
EZS(Electronic Ignition Lock Control Unit)	Q 1
KLA(Air Conditioner Control Unit)	Q 2
HU(Head Unit Control Unit)	3 2
AUTEL www.autel.com MaxiSys MS906 BT	Page 1

DSI(Shift Lever Control Unit)	3 2
DMFL(Left Front Door Control Unit)	3 2
DMFR(Right Front Door Control Unit)	3 2
DMRR(Right Rear Door Control Unit)	3 2
DMRL(Left Rear Door Control Unit)	3 2
ZBE(Head Unit Display)	3 2
ZAN(Center Display Control Unit)	Q 1
RBTMFR(Passenger Seat Belt Tensioner Control Unit)	Q 1
RBTMFL(Driver Seat Belt Tensioner Control Unit)	Q 1
MRM(Steering Column Control Unit)	Q 1
FSCU(Fuel Pump Control Unit)	3 2
CGW(Central Gateway Control Unit)	3 2

🔼 DTC (58)

ECM(Engine Control Unit) (9 DTCs)

DTC	Description	Status
P241429	The signal of oxygen sensor 1 (cylinder bank 1) is implausible. There is an invalid signal.	Active and stored
P001762	The position of the exhaust camshaft (cylinder bank 1) is implausible relative to the position of the crankshaft. The signal comparison is faulty.	Stored
P007200	The outside temperature sensor has a short circuit to ground.	Stored
P017127	The mixture (cylinder bank 1) is too lean. The signal change rate is above the permissible limit value.	Active and stored
P008777	The fuel pressure in the system is too low. The commanded position cannot be reached.	Stored
P008A23	The pressure in the fuel low pressure circuit is too low. No signal change: Voltage level is too low.	Stored
U012087	Communication with the starter or alternator has a malfunction. The message is missing.	Active and stored(Event codes)
P219522	The signal from oxygen sensor 1 (cylinder bank 1) is shifted towards 'Lean'. The signal amplitude is greater than the maximum amplitude.	Active and stored
P008A21	The pressure in the fuel low pressure circuit is too low. The signal amplitude is less than the minimum amplitude.	Stored
AUTEL ****	autel.com MaxiSys MS906 BT	Page 2

Report ID: MAXIA20231220161333

TCM(Transmission Control Unit) (1 DTC)

DTC	Description	Status
C002	CAN communication with further control units is not possible.	Stored
ESP(Electronic S	Stability Program Braking System) (2 DTCs)	
DTC	Description	Status
6001	The supply voltage of 'CC52 (Electronic stability program control module)' is too high (overvoltage).	Stored(Event codes)
6000	The supply voltage of 'CC52 (Electronic stability program control module)' is too low (undervoltage).	Stored(Event codes)
SRS(Supplemen	tal Restraint System Control Unit) (1 DTC)	
DTC	Description	Status
B210D00	The power supply is too low.	Stored(Event codes)
KI(Instrument C	uster) (3 DTCs)	
DTC	Description	Status
B210A84	The power supply in the system is too low. There is a signal below the permissible limit value.	Stored(Event codes)
B210D16	The power supply is too low. The limit value for electrical voltage has not been attained.	Stored(Event codes)
U140329	Implausible signal 'Fuel level' was received. There is an invalid signal.	Stored(Event codes)
PTS(Parking Sys	stem) (2 DTCs)	
DTC	Description	Status
A10A00	The power supply in the system is too low.	Stored
C43100	Implausible data were received from the front signal acquisition and actuation module.	Stored(Event codes)
SAMF(Front Sig	nal Acquisition Control Unit) (6 DTCs)	
DTC	Description	Status
B219400	The power supply of circuit 30 is < 7.5 V.	Stored
B219600	The power supply of circuit 30g is < 7.5 V.	Stored
B219700	The power supply of circuit 30g is < 8.5 V.	Stored
B219500	The power supply of circuit 30 is < 8.5 V.	Stored
B219116	The power supply of circuit 30g is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored

AUTEL www.autel.com

MaxiSys MS906 BT

Report ID: MAXIA20231220161333

Page 4

SAMR(Rear Signal Acquisition Control Unit) (9 DTCs)

`			
DTC	Description	Status	
B280215	Right outer stop lamp and tail lamp fault - open circuit or short circuit to positive	Active and stored	
B280015	Left outer stop lamp and tail lamp fault - open circuit or short circuit to positive	Active and stored	
B219600	The power supply of circuit 30g is < 7.5 V.	Stored	
B219700	The power supply of circuit 30g is < 8.5 V.	Stored	
B219116	The power supply of circuit 30g is outside the valid range. The limit value for electrical voltage has not been attained.	Stored	
B219400	The power supply of circuit 30 is < 7.5 V.	Stored	
B219500	The power supply of circuit 30 is < 8.5 V.	Stored	
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored	
B280115	Left inner stop lamp and tail lamp fault - open circuit or short circuit to positive	Active and stored	
EZS(Electronic	c Ignition Lock Control Unit) (1 DTC)		
DTC	Description	Status	
A10D00	The power supply is too low.	Stored	
KLA(Air Condi	tioner Control Unit) (2 DTCs)		
DTC	Description	Status	
A10A00	The power supply in the system is too low.	Stored(Event codes)	
A10D00	The power supply is too low.	Stored(Event codes)	
HU(Head Unit	Control Unit) (2 DTCs)		
DTC	Description	Status	
A10A	The power supply in the system is too low.	Stored(Event codes)	
A10D	The power supply is too low.	Stored(Event codes)	
DSI(Shift Leve	er Control Unit) (2 DTCs)		
DTC	Description	Status	
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)	
B210A00	The power supply in the system is too low.	Stored(Event codes)	
DMFL(Left Fro	ont Door Control Unit) (2 DTCs)		
DMFL(Left Fro	ont Door Control Unit) (2 DTCs) Description	Status	

A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)
DMFR(Right Fre	ont Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10A00	The power supply in the system is too low.	Stored(Event codes)
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
DMRR(Right Re	ear Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
A10A00	The power supply in the system is too low.	Stored(Event codes)
DMRL(Left Rea	r Door Control Unit) (2 DTCs)	
DTC	Description	Status
A10C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored
A10A00	The power supply in the system is too low.	Stored(Event codes)
ZBE(Head Unit	Display) (2 DTCs)	
DTC	Description	Status
A10A00	The power supply in the system is too low.	Stored(Event codes)
A10D00	The power supply is too low.	Stored(Event codes)
ZAN(Center Dis	play Control Unit) (1 DTC)	
DTC	Description	Status
A10A	The power supply in the system is too low.	Stored(Event codes)
RBTMFR(Passe	enger Seat Belt Tensioner Control Unit) (1 DTC)	
DTC	Description	Status
510116	The supply voltage of 'CB72 (Right front reversible emergency tensioning retractor)' is too low (undervoltage).	Stored
RBTMFL(Driver Seat Belt Tensioner Control Unit) (1 DTC)		
DTC	Description	Status
510116	The supply voltage of 'CB71 (Left front reversible emergency tensioning retractor)' is too low (undervoltage).	Stored(Event codes)
MRM(Steering Column Control Unit) (1 DTC)		
DTC	Description	Status
B210D00	The power supply is too low.	Stored(Event codes)

FSCU(Fuel Pump Control Unit) (2 DTCs)

DTC	Description	Status
A10D00	The power supply is too low.	Stored
254000	The signal for the pressure sensor of the low-pressure fuel circuit is implausible.	Stored
CGW(Central Gateway Control Unit) (2 DTCs)		
DTC	Description	Status
U103288	Chassis CAN communication has a malfunction. Bus OFF	Stored
B210A00	The power supply in the system is too low.	Stored

Technician Notes

2016206410

Customer name:

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

