



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/02/2024		M57 Pretoria Road - 1619
Inspection Date	22/02/2024		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	JEEP	Registration Number	CB86ZGGP
Model	COMPASS	Register Number	
VIN	1C4NJCDAA0CD606385	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2022
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	156,976 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Engine Management Lights Set	Repair
Windscreen Wiper Damaged	Replace
Park Light Front Right Defective	Replace
Tail Light Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Shock Absorber Front Left Worn	Repair
Shock Absorber Front Right Worn	Replace
Shock Absorber Rear Left Worn	Repair
Shock Absorber Rear Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Engine Performance Insufficient	Repair
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Minor dents and scratches and stone chips
Body and exterior	Poor alignment to some body panels.
Body and exterior	Vehicle body in poor condition.
Body and exterior	Repair work done to vehicle below-standard.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: 1C4NJCDAA0CD606385

1 / 12



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

### Brakes

#### Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	2.82	3.34	-	-
Rear	2.11	1.96	-	-
Emergency / Parking	2.04	1.92	-	-

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/55R18	99V	Continental	Contipremium	V	5218	0 mm
Front Right	215/55R18	99V	Continental	Contipremium	V	5218	0 mm
Rear Left	215/55R18	99V	Continental	Contipremium	V	5218	3 mm
Rear Right	215/55R18	99V	Continental	Contipremium	V	5218	3 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




## CONDITION REPORT

VIN: 1GNNNDL0A201629350 Report No: 201629350


2 / 12

DATE


22/02/2024




Brake test



diagnostics



diagnostics



diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



## CONDITION REPORT

Report No: 2016278730

VIN: 1C4NJCD606385

DATE

22/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016278730

DATE

VIN: 1C4NJCDAY22002024

22/02/2024

4 / 12



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

VIN: 1C4NJCD A0CD606385

5 / 12

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

VIN: 1C4NJCDAA0CD606385

6 / 12



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

VIN: 1C4NJCD606385

7 / 12

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

VIN PLATE OR STICKER



ENGINE 1

8 / 12



Chassis 1



Chassis 2



Oil cap and dipstick



Automatic.



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

VIN: 1C4NJFDA0CD606385

9 / 12



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Rear Left



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

VIN: 1C4NJCD606385

11 / 12



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

Door Front Left



Rear Fender Left

VIN: 1C4NJCDAA0CD606385  
12 / 12

Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)




## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

Door Front Right



Rear Fender Right



Front Fender Right



Tail Light Right



Park Light Front Right



Windscreen Wiper



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)




## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

Shock Absorber Rear Left



Shock Absorber Rear Right



Shock Absorber Front Left



Shock Absorber Front Right



Engine



Tyre Front Left



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

Tyre Front Right



## CONDITION REPORT

Report No: 2016278730

DATE  
22/02/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)