

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	08/03/2024		M57 Pretoria Road - 1619
Inspection Date	08/03/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	BT11MTGP
Model	POLO VIVO	Register Number	
VIN	AAVZZZ6SZCU020848	Date Of First Licensing	
Engine Number		Last COR	
Doors	3	License Expiry Date	30/06/2023
Color	RED	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	248,640 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

	Damage	Repair Way
	Engine Leak	Repair
	Seat Front Left Torn / Cut	Repair
	Seat Front Right Torn / Cut	Repair
	Side Mirror Left Damaged	Repair
	Side Mirror Right Damaged	Replace
	Parking Brake Performance Left / Right Difference out of legal range	Repair
	Tie Rod End left Damaged	Replace
	Shock Absorber Rear Right Sweat	Replace
	Stabilizer Mounting Front Right Damaged	Replace
	Tyre Front Left Smooth	Replace
	Tyre Front Right Smooth	Replace
	Tyre Rear Left Excessive Wear & Tear	Replace
	Rim Rear Left Scratched	Replace
	Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
	Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
	Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
	Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
	CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
	CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
	Engine Noise Excessive	Repair
	Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.7	2.6	-	
Rear	1.3	1.9	-	
Emergency / Parking	0.3	0.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R15	85V	Landsail	LS388	V	2017	0 mm
Front Right	195/55R15	85V	Landsail	LS388	V	2017	0 mm
Rear Left	195/55R15	85V	Landsail	LS388	V	0000	0 mm
Spare	185/60R15	84H	Bridgestone	Turanza	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: RESIDUAL TRACES OF POOR REPAIR WORK DONE ON VEHICLE. SIGNS OF SPRAY WORK DONE ON ALL BODY PANELS. ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



Expansion bottle



Oil cap and dipstick



Sparewheel



Rear end



Warning light illuminated



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



ENGINE 1



CHASSIS



ENGINE 2



VIN PLATE OR STICKER



LICENSE DISC

Car				MMA	
Model:	Car	Year:	2011	Make:	MAHLE
Registration:	277-2306	Engine:	1.8L	Model:	MAHLE
Test date:	18/11	Test time:	10:00	Test place:	MAHLE
Test results:					
Shock absorber				Result	Condition
Front left	1.0	1.0	1.0	1.0	1.0
Front right	1.0	1.0	1.0	1.0	1.0
Rear left	1.0	1.0	1.0	1.0	1.0
Rear right	1.0	1.0	1.0	1.0	1.0
Brake					
Front left	1.0	1.0	1.0	1.0	1.0
Front right	1.0	1.0	1.0	1.0	1.0
Rear left	1.0	1.0	1.0	1.0	1.0
Rear right	1.0	1.0	1.0	1.0	1.0

SHOCK & BRAKE REPORT

Car				MMA	
Model:	Car	Year:	2011	Make:	MAHLE
Registration:	277-2306	Engine:	1.8L	Model:	MAHLE
Test date:	18/11	Test time:	10:00	Test place:	MAHLE
Test results:					
Shock absorber				Result	Condition
Front left	1.0	1.0	1.0	1.0	1.0
Front right	1.0	1.0	1.0	1.0	1.0
Rear left	1.0	1.0	1.0	1.0	1.0
Rear right	1.0	1.0	1.0	1.0	1.0
Brake					
Front left	1.0	1.0	1.0	1.0	1.0
Front right	1.0	1.0	1.0	1.0	1.0
Rear left	1.0	1.0	1.0	1.0	1.0
Rear right	1.0	1.0	1.0	1.0	1.0

DIAGNOSTIC REPORT PAGE 1

Car				MMA	
Model:	Car	Year:	2011	Make:	MAHLE
Registration:	277-2306	Engine:	1.8L	Model:	MAHLE
Test date:	18/11	Test time:	10:00	Test place:	MAHLE
Test results:					
Shock absorber				Result	Condition
Front left	1.0	1.0	1.0	1.0	1.0
Front right	1.0	1.0	1.0	1.0	1.0
Rear left	1.0	1.0	1.0	1.0	1.0
Rear right	1.0	1.0	1.0	1.0	1.0
Brake					
Front left	1.0	1.0	1.0	1.0	1.0
Front right	1.0	1.0	1.0	1.0	1.0
Rear left	1.0	1.0	1.0	1.0	1.0
Rear right	1.0	1.0	1.0	1.0	1.0

DIAGNOSTIC REPORT PAGE 2



Water level



Engine



Bolt(s) / Nut(s) Front Wheel Right



Tyre Front Right



Stabilizer Mounting Front Right



Bolt(s) / Nut(s) Front Wheel Left



Tyre Front Left



Tyre Rear Left



Rim Rear Left



Bolt(s) / Nut(s) Rear Wheel Left



Bolt(s) / Nut(s) Rear Wheel Right



Tie Rod End left




CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Shock Absorber Rear Right



Side Mirror Left

Figure 1 shows a schematic diagram of a rectangular pond, 1000 m long and 10 m wide. The pond is divided into three sections: a 300 m section on the left, a 400 m section in the middle, and a 300 m section on the right. The left section contains a 'Pond aeration pump (1000 W)'. The middle section contains two 'Water pump' symbols. The right section contains two 'Water pump' symbols. The pond is labeled 'Pond' and '1000 m' at the top. The width is labeled '10 m' on the right side. The sections are labeled '300 m', '400 m', and '300 m' at the bottom. The water pump symbols are labeled 'Water pump' and 'Water pump'.


Parking Brake Performance



Seat Front Right



Seat Front Left



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za