



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	02/09/2025		M57 Pretoria Road - 1619
Inspection Date	02/09/2025		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	HVG956MP
Model	POLO VIVO GP 1.6 77KW MAXX 5-DR [2014-2016]	Register Number	
VIN	AAVZZZ6SZFU008157	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2025
Color	SILVER	Power / Displacement	
Year Model	2014	Paint Finish	TWO COAT METALLIC
Km Reading	207,985 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



Damage	Repair Way
Engine Damaged	Replace
Hoses Damaged	Replace
Radio/CD/USB Damaged	Replace
Headlight Left Damaged	Repair
Headlight Right Damaged	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Sun Visor Right Damaged	Repair
Parcel Tray Damaged	Repair
Side Mirror Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Shock Absorber Front Right Damaged	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Sub Frame Damaged	Repair
Engine to silencer pipe Welded	Replace
Silencer Missing	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Warning light illuminated	Repair

## Brakes

## Brake Test Results

	Left	Right	Axe Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	2.39	2.63	-	
Rear	1.16	1.94	-	
Emergency / Parking	0.12	0.94	-	

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81S	Bridgestone	Radial	V	3617	0 mm
Front Right	175/65R14	82T	Bridgestone	Radial	V	1516	0 mm
Rear Left	175/65R14	86H	Radar	Radial	V	1123	0 mm
Rear Right	215/40R17	87V	Continental	Contipremiu	V	2217	1 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Signs of impact damage to front of vehicle.

Brakes: rear tire sizes do not match.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157




## CONDITION REPORT




Report No:  
2016999506  
DATE  
02/09/2025



Brake test.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



Hoses



Hoses



Headlight Left



Headlight Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



Bonnet



Front Fender Left



Rear Fender Left



Front Fender Right



Rear Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



Door Rear Right



Rear bumper



Boot Lid / Hatch door



Seat Rear



Parcel Tray



Seat Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025




Seat Front Left



Sun Visor Right



Side Mirror Right



Radio/CD/USB



Tyre Rear Left



Tyre Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025




Tyre Front Right



CV Joint(s) Boot(s) Front Right (inner/outer)




CV Joint(s) Boot(s) Front Left (inner/outer)



Radiator Cradle



Shock Absorber Front Right



Engine

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157



## CONDITION REPORT



Report No:  
2016999506  
DATE  
02/09/2025



Engine



Sub Frame



Engine to silencer pipe



Silencer

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZ6SZFU008157