



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/05/2025		M57 Pretoria Road - 1619
Inspection Date	07/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	CHEVROLET	Registration Number	JYM007MP
Model	UTILITY 1.8 SPORT PU [2011-2017]	Register Number	
VIN	ADMCF80HED4613130	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	
Color	BROWN	Power / Displacement	
Year Model	2013	Paint Finish	M - METALLIC
Km Reading	282,339 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Air cleaner Damaged	Replace
Dim Light Left Malfunction	Repair
Dim Light Right Malfunction	Repair
Fog Light Front Left Malfunction	Repair
Fog Light Front Right Malfunction	Repair
Seat Front Right Torn / Cut	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Roof Paintwork • Discoloured	Repair
Windscreen Cracked	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

Damage	Repair Way
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Front Right Damaged	Replace
Gearbox Mountings Cracked	Replace
Gearbox Oil Leak	Repair
Engine Performance Idling / Hunting	Repair
Gear Selections Insufficient	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Signs of spray work done on some body panels
Body exterior	Discoloring on some body panels
No license disc	Replace
Battery loose	Repair
Aftermarket exhaust fitted	Repair
L/F fender liner damage	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.0	2.0	-	
Rear	0.1	2.4	-	
Emergency / Parking	1.4	0.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/50R15	86V	Fortune	Perfectus	V	1123	3 mm
Front Right	195/50R15	82W	Sumitomo	Htr	V	1717	0 mm
Rear Left	195/50R15	82V	Dunlop	Sp sport	V	1922	1 mm
Rear Right	195/50R15	82V	Dunlop	Sp sport	V	1922	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	DTC HISTORY	P0036:00	HEATED OXYGEN SENSOR HEATER CONTROL CIRCUIT SENSOR	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: ADMCF80HED4613130

**CONDITION REPORT****Report No: 2016868717****DATE**
07/05/2025

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT


Report No: 2016868717

DATE
07/05/2025

Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130




CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel covered

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Battery loose

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT


Report No: 2016868717

DATE
07/05/2025


Oil cap and dipstick



Expection bottle



Parking Brake Performance



Service Brake Performance Rear Axle



Water level



Air cleaner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

Bonnet



Windscreen



Roof



Seat Front Right



Rear Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025


Tailgate



Rear bumper



Rear bumper



Tyre Front Right



Engine



Gearbox Mountings

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130



CONDITION REPORT

Report No: 2016868717

DATE
07/05/2025

Gearbox



Dim Light Left



Dim Light Right



Fog Light Front Left



Fog Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HED4613130