



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	06/08/2024		M57 Pretoria Road - 1619
Inspection Date	06/08/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	CHEVROLET	Registration Number	JDR491MP
Model	UTILITY	Register Number	
VIN	ADMJF4MR5G4782160	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/08/2023
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	78,321 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Damaged	Repair
Engine Wiring Defective	Repair
Hoses Oil Sweat	Replace
Battery clamps Defective	Repair
Wiring connections Defective	Repair
Seat Front Right Torn / Cut	Repair
Side Mirror Left Damaged	Repair
Front Bumper Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Sill Panel Left Residual Traces of Repair	Repair
Load Body Paintwork • Scratched	Repair
Steering Rack Boot Left Torn / Cut	Replace
Spring Front Left Defective	Replace
Spring Front Right Defective	Repair
Spring Rear Left Incorrect	Replace
Spring Rear Right Incorrect	Replace
Shock Absorber Front Left Leak	Replace
Alignment Left / Right Difference out of legal range	Repair
Ball Joint(s) Front Axle Left Damaged	Replace
Tyre Front Left Excessive Wear & Tear	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Excessive Wear & Tear	Replace
Rim Rear Right Damaged	Repair
Gearbox Oil Leak	Repair
Front tyre size differs	Replace.
Vehicle electronics malfunction.	Repair.
Engine light goes on and goes off	Repair.
L/F shock weak	Replace.
Rear tyre size differs	Replace.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMJF4MR5G4782160

1 / 13



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

Damage	Repair Way
oil sludge on oil cap.	Repair.
Lower suspension fitted to vehicle	Replace

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.4	1.9	-	
Rear	1.0	1.2	-	
Emergency / Parking	0.9	0.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/40R17	87W	Tracmak	Privilo	V	0000	0 mm
Front Right	195/50R15	82V	Sumitomo	HTR	V	4218	3 mm
Rear Left	215/45R17	91W	Continental	Contact	V	2420	1 mm
Rear Right	225/45R17	91W	Falken	Ziex	V	4118	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Vehicle doesn't start
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Residual traces of repair work done on some body panels. Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

VIN: ADM1F4MREG4782160
Report No: 2016481849
2 / 13
DATE
06/08/2024

Shock and brake	
Vehicle	2016 Chevrolet Spark
Engine	1.4L
Transmission	5-speed manual
Drive	FWD
Weight	1100 kg
Wheelbase	2450 mm
Track	1450 mm
Brake	Disc
Shock absorber	Coil over
Steering	Rack and pinion
Exhaust	2.0L
Engine	1.4L
Transmission	5-speed manual
Drive	FWD
Weight	1100 kg
Wheelbase	2450 mm
Track	1450 mm
Brake	Disc
Shock absorber	Coil over
Steering	Rack and pinion
Exhaust	2.0L

Shock and brake

Diagnostic test	
Vehicle	2016 Chevrolet Spark
Engine	1.4L
Transmission	5-speed manual
Drive	FWD
Weight	1100 kg
Wheelbase	2450 mm
Track	1450 mm
Brake	Disc
Shock absorber	Coil over
Steering	Rack and pinion
Exhaust	2.0L
Engine	1.4L
Transmission	5-speed manual
Drive	FWD
Weight	1100 kg
Wheelbase	2450 mm
Track	1450 mm
Brake	Disc
Shock absorber	Coil over
Steering	Rack and pinion
Exhaust	2.0L


Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849
VIN: ADMJF4MR5G4782160
DATE
06/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
VIN: ADMJF4MR5G4782160
06/08/2024
4/13

ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016481849

DATE

06/08/2024

VIN: ADMJF4MR5G4782160

5 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

VIN: ADMJF4MR5G4782160

6 / 13



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No sparewheel



LICENSE DISC



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

VIN: ADMJF4MR5G4782160
7 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



Rear end



CHASSIS



Expansion bottle



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

VIN: ADMJF4MR5G4782160
9 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

Oil cap and dipstick



Wiring connections

VIN: ADMJF4MR5G4782160

10 / 13



Wiring connections



Wiring connections



Seat Front Right



Water level



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

VIN: ADMJF4MR5G4782160
11 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

Engine Wiring



Gearbox

VIN: ADMJF41P55G4782160

12 / 13



Steering Rack Boot Left



Spring Front Right



Front Bumper



Front Bumper



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

VIN: ADMJF4MR5G4782160
13 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

Engine Wiring



Tyre Front Left



Spring Front Left



Shock Absorber Front Left



Load Body



Load Body



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

Rear bumper



Rear bumper



Load Body



Tyre Front Right



Engine



Hoses



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

Ball Joint(s) Front Axle Left



Gearbox



Sill Panel Left



Sill Panel Left



Tyre Rear Left



Rim Rear Right



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


Report No: 2016481849

DATE
06/08/2024

Spring Rear Left



Spring Rear Right



Battery clamps



Side Mirror Left



CONDITION REPORT

Report No: 2016481849

DATE
06/08/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za