



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	05/01/2024		M57 Pretoria Road - 1619
Inspection Date	05/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	HX72GTGP
Model	NP200	Register Number	
VIN	ADNUSN1D5U0154645	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/05/2023
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	95,228 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Damaged	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Damaged	Repair
Hood Lining Dirty	Repair
Door Panel Front Right Damaged	Repair
Clutch Pedal Rubber Torn / Cut	Replace
Steering Wheel Trim Defective	Repair
Number Plate Front Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
B • Pillar Left Dented	Repair
B • Pillar Right Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Tailgate Damaged	Replace
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Rocker Panel Right Damaged	Repair
Roof Dented	Repair
Load Body Paintwork • Scratched	Repair
Windscreen Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0154645

1 / 15



CONDITION REPORT

Report No: 2016218774

 DATE
05/01/2024

Damage	Repair Way
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	
Steering box Leak	Repair
Tie Rod End left Damaged	Replace
Steering Rack Boot Left Sweat	Replace
Rear Axle Defective	Repair
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Rear Right Torn / Cut	Replace
Chassis Scratched	Repair
Belly plates Defective	Repair
Gearbox Oil Sweat	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.63	2.24	-	
Rear	1.73	2.07	-	
Emergency / Parking	1	1.52	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	92T	Barum	Brillantis	V	1921	5 mm
Front Right	185/65 R15	92T	Barum	Brillantis	V	1422	6 mm
Rear Left	185/65 R15	92T	Barum	Brillantis	V	0721	1 mm
Rear Right	185/65 R15	92T	Barum	Brillantis	V	3118	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BCM	P0000	FRONT WINDSHIELD WIPER PARK CIRCUIT	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. SHOCK ABSORBER TEST COULD NOT BE PERFORMED. Engine Compartment: Engine bay dirty. Brake fluid level ok.
 Electrical Components and I

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za



CONDITION REPORT

VIN: SAUW1D51625674
Report No: 2016218774
2 / 15
DATE
05/01/2024

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

VIN: ADNUSN1D5U0154645

DATE
3/15
05/01/2024

Client		Vehicle		Test	
Name	Mr. M. M. M.	Model	BMW 3 Series	Year	2015
Registration	12345678	Engine	2.0L	Power	150 kW
Test Date	05/01/2024	Tester	John Doe	Station	DEKRA
Test Result	Pass	Remarks	Brake system in good condition.		

Brake test report



Front chassis



Rear chassis

System	Component	Status	Notes
Engine	Oil Pressure	OK	
Engine	Water Temp	OK	
Engine	Oil Level	OK	
Engine	Water Level	OK	
Engine	Oil Pressure	OK	
Engine	Water Temp	OK	
Engine	Oil Level	OK	
Engine	Water Level	OK	
Engine	Oil Pressure	OK	
Engine	Water Temp	OK	
Engine	Oil Level	OK	
Engine	Water Level	OK	

Diagnostic report page 1

System	Component	Status	Notes
Engine	Oil Pressure	OK	
Engine	Water Temp	OK	
Engine	Oil Level	OK	
Engine	Water Level	OK	
Engine	Oil Pressure	OK	
Engine	Water Temp	OK	
Engine	Oil Level	OK	
Engine	Water Level	OK	
Engine	Oil Pressure	OK	
Engine	Water Temp	OK	
Engine	Oil Level	OK	
Engine	Water Level	OK	

Diagnostic report page 2



Oil cap and dipstick



CONDITION REPORT

Report No: 2016218774

DATE
VIN: ADNUSN1D510152024
05/01/2024
4 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645

5 / 15



Manual Transmission



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645
6 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645

7 / 15



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645
8 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645
10 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Steering Wheel Trim



Door Panel Front Right



Seat Front Right



B • Pillar Right



Sill Panel Right



Door Front Right



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645
12 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Rear Fender Right



Rear bumper



Rear bumper



Tail Light Left



Tailgate



Load Body



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

VIN: ADNUSN1D5U0154645
14 / 15

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Rear Fender Left



Rear Fender Left



Door Front Left



Front Fender Left



Windscreen



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Front Bumper



Front Bumper



Bonnet



Number Plate Front



Front Fender Right



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Clutch Pedal Rubber



B • Pillar Left



Seat Front Left



Sill Panel Left



Water level



Rocker Panel Right



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Tyre Rear Right



Rear bumper



Belly plates



Engine



Gearbox



Chassis



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Rear Axle



Tie Rod End left



Steering box



Steering Rack Boot Left



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024



Engine Wiring



CONDITION REPORT

Report No: 2016218774

DATE
05/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za