



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	15/05/2025		M57 Pretoria Road - 1619
Inspection Date	15/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	NISSAN	Registration Number	HX25YJGP
Model	NP200 1.5DCI BASE +AC SAFETY DSL PU [2014-2022]	Register Number	
VIN	ADNUSN365U0160767	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	C - COMMON
Km Reading	237,246 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Sweat	Repair
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Door Front Right Dented	Repair
Tailgate Damaged	Replace
Rear bumper Damaged	Repair
Load Body Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Brake Piping Torn / Cut	Replace
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Rear Right Smooth	Replace
Rim Front Left Dented	Repair
Rim Rear Right Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

Damage	Repair Way
Warning lights illuminated	Repair
Rear tyres size differs	Replace

Brakes**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.4	3.2	-	
Rear	1.5	0.0	-	
Emergency / Parking	0	0	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	92T	Dunlop	Sport	V	0000	1 mm
Front Right	185/65R15	92T	Barum	Brillantis	V	9589	3 mm
Rear Left	195/65R15	91H	Continental	Control	V	0000	1 mm
Rear Right	185/65R15	92H	Sumitomo	HTR	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P0380	PREHEATING UNIT DIAGNOSIS CONNECTION	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Bottom of engine is fully covered.
 Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksdorp, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767




CONDITION REPORT


Report No: 2016879026

DATE
15/05/2025

Shock and brake report



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025


90 DEGREE LEFT



LF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No license disc

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767




CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear end



No sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

Expansion bottle



Oil cap and dipstick




ABS warning lights illuminated



Seat Front Left



Windscreen



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

Bonnet



Water level



Engine



Grill



Front Bumper



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

Load Body



Rear bumper



Tailgate



Tailgate



Rim Front Left



Brake Piping

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

Engine



Engine



Tyre Rear Right



Rim Rear Right



Door Front Right

	Front Left	Front Right	Rear Left	Rear Right
Front Left	140	140	140	140
Front Right	140	140	140	140
Rear Left	140	140	140	140
Rear Right	140	140	140	140

Parking Brake Performance




DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767



CONDITION REPORT

Report No: 2016879026

DATE
15/05/2025

Service Brake Performance Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN365U0160767