



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	14/12/2023		M57 Pretoria Road - 1619
Inspection Date	14/12/2023		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	JK80RGGP
Model	COROLLA	Register Number	
VIN	AHTBB0JE800022005	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2024
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	47,121 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Windscreen Wiper Defective	Replace
Headlight Left Broken	Replace
Seat Rear Defective	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Bonnet slam plate (Shock tower/ Inner tray) Residual Traces of Repair	Repair
C • Pillar Left Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Rear Fender Left / Inner Tray Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Dented	Repair
Roof Dented	Repair
Windscreen Defective	Repair
Brake disc 2. Axle left Defective	Replace
Brake disc 2. Axle right Defective	Replace
Chassis Scratched	Repair
Belly plates Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBB0JE800022005

1 / 13



CONDITION REPORT

Report No: 2016202109

 DATE
14/12/2023

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.48	3.72	-	
Rear	2.63	3.08	-	
Emergency / Parking	1.39	1.59	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55 R16	91V	Continental	Sport	V	3717	2 mm
Front Right	205/55 R16	91V	Continental	Sport	V	3717	3 mm
Rear Left	205/55 R16	91V	Continental	Sport	V	3717	5 mm
Rear Right	205/55 R16	91V	Continental	Sport	V	3717	6 mm
Spare	205/55 R16	91V	Continental	Sport	V	3817	7 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P1604	STARTABILITY FAULT	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Engine Compartment: Engine bay dirty. Brake fluid level ok.

Interior: Vehicle interior dirty and some interior panels scratched. Rear left panic handle missing.

Body • Exterior: Minor dents and scratches on some body panels. Spray work on some body panels. Some body panels misaligned. Stone chips on some body panels. Front emblem missing. Residual traces of repair on some body panels. Signs of hail damage on some body panels . Signs of impact damage to front and rear of vehicle.

Axle and Suspension: Abnormal noise coming from front and rear suspension.

Tyres and Rims: Alloy rims scratched.

Undercarriage: Vehicle undercarriage dirty. Centre exhaust bracket scratched.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE




Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za





CONDITION REPORT

Report No: 2016202109

VIN: AHTBB0JE800022005
DATE
3/13
14/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE 18/02/2023
 VIN: AHTBB0JF800020023
 4 / 13



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN: AHTBB0JE800022005

5 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN: AHTBB0JE800022005

6 / 13



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN: AHTBB0JE800022005
7 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN PLATE OR STICKER



ENGINE 1

VIN: AHTB00JE800022005

8 / 13



Front chassis



Rear chassis



Oil cap and dipstick



Automatic Transmission



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN: AHTBB0JE800022005
9 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

Seat Rear



Seat Rear



Windscreen Wiper



Front Bumper



Front Bumper



Bonnet



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN: AHTBB0JE800022005
11 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

Sill Panel Right



C • Pillar Left



Headlight Left



Front Fender Right



Door Front Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

VIN: AHTBB0JE800022005
13 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

Door Rear Right



Rear Fender Right



Brake disc 2. Axle right



Rear bumper



Rear bumper



Rear Fender Left



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

Brake disc 2. Axle left



Door Rear Left



Door Front Left



Front Fender Left



Belly plates



Rear Fender Left / Inner Tray



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

Chassis



Water level



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Boot Lid / Hatch door



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016202109

DATE
14/12/2023

Roof



Windscreen

**CONDITION REPORT****Report No: 2016202109****DATE**
14/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za