



**CONDITION REPORT**

Report No: 2016803774

DATE  
17/03/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



**Assignment**

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 17/03/2025        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 17/03/2025        |                     | Kempton Park - GT        |

**Vehicle Data**

|                 |   |                         |              |
|-----------------|---|-------------------------|--------------|
| Vehicle Type    | LIGHT LOAD VEHICLE  | Registered Owner        | MFC          |
| Manufacturer    | TOYOTA  | Registration Number     | JZG046MP     |
| Model           | HILUX LEGEND45 2.5 D-4D RB RAIDER D-CAB<br>DSL PU [2014-2016] | Register Number         |              |
| VIN             | AHTER39G008606805   | Date Of First Licensing |              |
| Engine Number   |   | Last COR                |              |
| Doors           | 4   | License Expiry Date     | 17/03/2025   |
| Color           | WHITE   | Power / Displacement    |              |
| Year Model      | 2015  | Paint Finish            | TWO COAT UNI |
| Km Reading      | 270,446 KM  | Fuel                    | DIESEL       |
| Cab / Body Type | DOUBLE CAB  | Transmission            | MANUAL       |

**Vehicle Options & Accessories**

**Items**

VEHICLE INSPECTION

|                       | Damage                                     | Repair Way |
|-----------------------|--|------------|
|                       | Engine Oil Sweat                           | Repair     |
|                       | Seat Front Right Damaged                   | Repair     |
|                       | Front Bumper Damaged                       | Repair     |
|                       | Bonnet Damaged                             | Repair     |
|                       | C • Pillar Right Damaged                   | Repair     |
|                       | Front Fender Left Damaged                  | Repair     |
|                       | Front Fender Right Damaged                 | Repair     |
|                       | Rear Fender Left Damaged                   | Repair     |
|                       | Rear Fender Right Damaged                  | Repair     |
|                       | Door Front Left Damaged                    | Repair     |
|                       | Door Rear Left Damaged                     | Repair     |
|                       | Tailgate Damaged                           | Repair     |
|                       | Rear bumper Damaged                        | Repair     |
|                       | Roof Damaged                               | Repair     |
|                       | Shock Absorber Front Left Damaged          | Replace    |
|                       | Control Arm Bush(es) Front Axle Left Worn  | Repair     |
|                       | Control Arm Bush(es) Front Axle Right Worn | Replace    |
| Tyre Front Left Worn  | Replace                                    |            |
| Tyre Front Right Worn | Replace                                    |            |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTER39G008606805



## CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

| Damage               | Repair Way |
|----------------------|------------|
| Tyre Rear Right Worn | Replace    |
| Gearbox Oil Leak     | Repair     |

### Brakes

#### Brake Test Results

|                     | Left               | Right              | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] |                  |                                  |
| Front               | 3.55               | 3.85               | -                |                                  |
| Rear                | 2.47               | 2.1                | -                |                                  |
| Emergency / Parking | 2.86               | 1.62               | -                |                                  |

### Tyres and Rims

#### Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model  | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|--------|-------|-----------------|------------------|
| Front Left  | 265/65R17 | 112S             | Bridgestone | Radial | V     | 1521            | 0 mm             |
| Front Right | 265/65R17 | 112S             | Bridgestone | Radial | V     | 4321            | 0 mm             |
| Rear Left   | 265/65R17 | 112H             | Yokohama    | Radial | V     | 3619            | 1 mm             |
| Rear Right  | 265/65R17 | 120S             | BFGoodrich  | Radial | V     | 3119            | 0 mm             |

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System         | Code  | Description        | Status |
|----|----------------|-------|--------------------|--------|
| 1  | ENGINE AND ECT | P1604 | STARTABILITY FAULT |        |

### Inspection Conditions

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches to some body panels. Poor alignment to somebody panels. Signs of repair work done to somebody panels.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

VIN: AHTER39G008606805

2 / 10


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



Brake and shock test



Diagnostics

VIN: AHTER39G008606805

3 / 10



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

VIN: AHTER39G008606805

4 / 10

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT

VIN: AHTER39G008606805

5 / 10



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

VIN: AHTER39G008606805

6 / 10

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



NO LICENSE DISC



VIN PLATE OR STICKER

VIN: AHTER39G008606805

7 / 10

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTER39G008606805

8 / 10



CONDITION REPORT

Report No: 2016803774


DATE  
17/03/2025



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE

17/03/2025

VIN: AHTER39G008606805

9 / 10

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



Bonnet



Front Fender Left

VIN: AHTER39G008606805  
10 / 10



Door Front Left



Door Rear Left



Rear Fender Left



Tailgate

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



Rear bumper



Rear Fender Right



Front Fender Right



C • Pillar Right



Roof



Seat Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



Tyre Rear Right



Tyre Front Left



Tyre Front Right



Shock Absorber Front Left



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016803774

DATE  
17/03/2025



DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016803774**

**DATE**  
**17/03/2025**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za