



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	05/06/2025		M57 Pretoria Road - 1619
Inspection Date	05/06/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	FZT446L
Model	HILUX 2.8 GD-6 RB RAIDER D-CAB DSL PU AT [2016-2018]	Register Number	
VIN	AHTGA3DD600966785	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/07/2025
Color	GREY	Power / Displacement	
Year Model	2017	Paint Finish	M - METALLIC
Km Reading	168,707 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



Damage

Repair Way

Engine Oil Sweat	Repair
Dim and Bright Indicator Light Malfunction	Repair
Fog Light Front Right Malfunction	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Stabilizer Mounting Front Left Damaged	Repair
Spare Tyre Smooth	Replace
Gearbox Oil Sweat	Repair
Oil cap damage	Replace
ABS and traction control, brake pads light on	Repair
Extra spare wheel in load body	Repair
Rear tires deferred name brand and sizes	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.8	4.0	-	
Rear	3.3	2.7	-	
Emergency / Parking	2.4	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112S	Bridgestone	Dueller	V	0321	3 mm
Front Right	265/65R17	112S	Bridgestone	Dueller	V	0321	4 mm
Rear Left	245/65R17	111T	Ling long	Crosswind	V	2521	4 mm
Rear Right	265/65R17	112S	Dunlop	Grandtrek	V	3919	2 mm
2 Rear Left In	185/70R14	88T	Goodyear	Assurance	V	////	5 mm
Spare	265/65R17	112S	Dunlop	Grandtrek	V	0718	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/VSR/TRC	C1407	RIGHT REAR SPEED SENSOR CIRCUIT OPEN OR SHORT	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Vehicle got minor scratches, stone chips and dents.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTGA3DD600966785




CONDITION REPORT




Report No:
2016903257
DATE
05/06/2025



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785




CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



LICENSE DISC




VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025




Coolant bottle



Water level



Windscreen



Parking Brake Performance



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



Door Rear Left



Rear Fender Left



Tailgate



Rear bumper



Spare Tyre



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785



CONDITION REPORT



Report No:
2016903257
DATE
05/06/2025



Engine



Gearbox



Stabilizer Mounting Front Left



Bonnet



Dim and Bright Indicator Light



Fog Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTGA3DD600966785