



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	27/06/2025		M57 Pretoria Road - 1619
Inspection Date	27/06/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	JPG682MP
Model	HILUX 2.4 GD-6 RB SRX D-CAB DSL PU [2018-2020]	Register Number	
VIN	AHTJB8DDX04755825	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/10/2025
Color	WHITE	Power / Displacement	
Year Model	2018	Paint Finish	TWO COAT UNI
Km Reading	109,928 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



Damage	Repair Way
Engine Wiring Defective	Repair
Indicator Light Front Left Cracked	Replace
Door Panel Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Load Body Dented	Repair
Shock Absorber Mounting Rear Right Cracked	Replace
Belly plates Damaged	Repair
Gearbox Oil Sweat	Repair
Axle and suspension	Non standard lift kit fitted to vehicle.
Undercarriage	Vehicle undercarriage dirty
Body and Exterior	Poor residual traces of repair on some body panels
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Engine	Engine bay dirty.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.8	4.3	-	
Rear	3.27	3.65	-	
Emergency / Parking	2.75	2.12	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65 R17	112S	Bridgestone	Dueler	V	0224	7 mm
Front Right	265/65 R17	112S	Bridgestone	Dueler	V	0224	7 mm
Rear Left	265/65 R17	112S	Bridgestone	Dueler	V	3524	8 mm
Rear Right	265/65 R17	112S	Bridgestone	Dueler	V	0224	7 mm
Spare	265/65 R17	112H	Yokohama	Geolander	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P1604	STARTABILITY FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025

[illegible]

Brake and shock absorber repor

[illegible]

Diagnostic report page 1

Vehicle ID: 17097616	Test Time: 2025-05-27 15:22:57	Report ID: BAK5630256477152257
U0100	Engine/EV ECU communication	History
C1622	Rear camera disconnected	History

Technician Notes
2376907894

Customer name: _____
 Technician: _____
 Date: _____

Please bring a copy of this report for your records.

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



Oil cap and dipstick



Spare wheel Accessories



Load Body



Tailgate



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Sill Panel Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT




Report No:
2016927884
DATE
27/06/2025




Door Panel Front Right



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825



CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



Front Bumper



Front Bumper



Bonnet



Engine Wiring



Water level



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825




CONDITION REPORT



Report No:
2016927884
DATE
27/06/2025



Front Bumper



Belly plates



Gearbox



Shock Absorber Mounting Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB8DDX04755825