



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	
Requested Date	24/06/2025		M57 Pretoria Road - 1619
Inspection Date	24/06/2025		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	HY82LJGP
Model	COROLLA QUEST 1.6 PLUS [2016-2021]	Register Number	
VIN	AHTLB52E503140432	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2021
Color	SILVER	Power / Displacement	
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	103,466 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

**Vehicle Options & Accessories****Items****VEHICLE INSPECTION**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



Damage	Repair Way
Headlight Left Damaged	Replace
Gear Lever Dust Boot Defective	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Chipmarks	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Tyre Rear Right Damaged	Replace
Gearbox Oil Leak	Repair
Rear hub cap missing	Replace
R/F fender liner missing	Replace
Rear tires deferred name brand	Repair

## Brakes

## Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [kN]	Braking Force [kN]		
Front	3.0	2.8	-	
Rear	1.9	1.6	-	
Emergency / Parking	1.4	1.3	-	

## Tyres and Rims

## Tyre Specification &amp; Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65R15	91H	Continental	Contact	V	4222	1 mm
Front Right	195/65R15	91H	Continental	Contact	V	4222	1 mm
Rear Left	195/65R15	91H	Goodyear	Excellence	V	4718	2 mm
Rear Right	195/65R15	91H	Crosa 65	Radial	V	4912	3 mm
Spare	195/65R15	91H	Goodyear	Excellence	V	////	2 mm

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025

### **Diagnostic**

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	C1241	LOW OR HIGH POWER SUPPLY VOLTAGE	

### **Inspection Conditions**

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### **Comments**

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### **Concluding Remarks**

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### **Technician**

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



Coolant bottle



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT




Report No:  
2016923142  
DATE  
24/06/2025



CHASSIS




ENGINE 2




VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za


VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



DIAGNOSTIC REPORT PAGE 2



Water level



Headlight Left



Bonnet



Windscreen



Rear Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



Door Rear Right



Door Front Right



Side Mirror Right



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTLB52E503140432



## CONDITION REPORT



Report No:  
2016923142  
DATE  
24/06/2025



Tyre Rear Right



Gearbox



Gear Lever Dust Boot

DEKRA Automotive (PTY) Ltd.

97 Willem Cruywagen Ave

Klerksdorp, Pretoria, 0200

Phone: 012 542 4867

www.dekraauto.co.za

VIN: AHTLB52E503140432