

Shop: DEKRA MFC Tel: --Email: --Address: MFC Auction House Kempton Park Report ID: MAXIA20240109134408 Test Time: 2024-01-09 13:44:08 Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information	
/Volkswagen/Cross Polo/	Odometer Reading: 177346km
VIN: AAVZZZ6RZFU039856	License Plate: KPY432MP
Customer Information	
Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE	Tel: 0861033572
Device information	
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01482
Version: V19.00	Repair Order Number:

🔁 System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	🔇 5
03 - Brakes 1	🔇 5
08 - Air Conditioning	o
09 - Electronic central electric	Q 4
15 - Airbag	3 2
17 - Instrument cluster	3 2
19 - Gateway	Q 1
44 - Power Steering	o
55 - Headlight Regulation	3 2
5F - Information electronics 1	3

🔼 DTC (24)

01 - Engine Control Module 1 (5 DTCs)

DTC	Description	Status
P190D00	Coolant pump for charge pressure cooler Mechanical malfunction	Passive/Sporadic
P011800	Coolant temperature sensor 1 Circuit high	Active/static
P014000	O2 Sensor Circ.,Bank1-Sensor2 No Activity Detected	Active/static
P014100	O2 Sensor Heater Circ.,Bank1-Sensor2 Malfunction	Active/static

Test Time: 2024-01-09 13:44:08

Report ID: MAXIA20240109134408

P003600	O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 2)	Passive/Sporadic		
03 - Brakes 1 (5 DTCs)				
DTC	Description	Status		
C114602	TPMS Signal error	Active/static		
C102D00	Tire pressure warning	Active/static		
U112300	Databus error value received	Active/static		
U112200	Data bus message implausible	Active/static		
U042300	Invalid data received from Instrument cluster control unit	Active/static		
09 - Electroni	c central electric (4 DTCs)			
DTC	Description	Status		
U101100	Supply voltage Voltage too low	Passive/Sporadic		
U140000	Function restriction Caused by low voltage	Passive/Sporadic		
B103F1B	Exterior temperature sensor Resistance too high	Active/static		
B1330F5	Anti-theft alarm system sensor Alert - emergency activation stage 1	Active/static		
15 - Airbag (2	2 DTCs)			
DTC	Description	Status		
B13BCF2	Multiple collision brake No function	Passive/Sporadic		
U101100	Supply voltage Voltage too low	Passive/Sporadic		
17 - Instrume	nt cluster (2 DTCs)			
DTC	Description	Status		
U101100	Supply voltage Voltage too low	Passive/Sporadic		
U112300	Databus error value received	Active/static		
19 - Gateway	(1 DTC)			
DTC	Description	Status		
U101100	Supply voltage Voltage too low	Passive/Sporadic		
55 - Headlight Regulation (2 DTCs)				
DTC	Description	Status		

/Volkswagen/Cross Polo		Test Time: 2024-01-09 13:44:08	Report ID: MAXIA20240109134408	
U140000	Function restriction Caused by low voltage		Passive/Sporadic	
U101100	Supply voltage Voltage too low		Passive/Sporadic	
5F - Information electronics 1 (3 DTCs)				
DTC	Description		Status	
U101100	Supply voltage Voltage too low		Passive/Sporadic	
B201A00	Check online function		Active/static	
B1297F5	Multimedia system displa Below supply voltage low	y unit 1 er limit	Passive/Sporadic	

Technician Notes

2016222268

Customer name:

Technician: _____

Date:

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.