



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241218093815
Test Time: 2024-12-18 09:38:15
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTCR32G708018921
Odometer Reading: 376678
License Plate: JW818NW

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.10
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine	✓ 0
ABS/VSC/TRC	✗ 8
SRS airbag	✗ 12
Cruise control	ADAS ✓ 0
Immobilizer	✓ 0

DTC (20)

ABS/VSC/TRC (8 DTCs)

DTC	Description	Status
C0200	Right front speed sensor circuit	Current
C0205	Left front speed sensor circuit	Current
C0210	Right rear speed sensor circuit	Current
C0215	Left rear speed sensor circuit	Current
C1236	Foreign object attached on tip of left front speed sensor	Current
C1241	Low battery positive voltage or abnormally high battery positive voltage	Current
C1244	Deceleration sensor circuit open or short	Current
C1249	Stop lamp switch circuit open	Current

SRS airbag (12 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current



/Toyota/Hilux		Test Time: 2024-12-18 09:38:15	Report ID: MAXIA20241218093815
B1803	Driver squib circuit short to battery (+)	Current	
B1901	Pretensioner squib (driver side) circuit open	Current	
B1906	Pretensioner squib (passenger side) circuit open	Current	
B1610	Right front airbag sensor	History	
B1615	Left front airbag sensor	History	
B1800	Driver squib circuit short	History	
B1801	Driving side squib circuit open	History	
B1803	Driver squib circuit short to battery (+)	History	
B1806	P squib circuit open	History	
B1901	Pretensioner squib (driver side) circuit open	History	
B1906	Pretensioner squib (passenger side) circuit open	History	

Technician Notes

2016664530

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

