

Shop Name: --Tel: --Email: --Address: --

Report ID: MAXIA20250605111340 Test Time: 2025-06-05 11:13:40

Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--Odometer Reading: 168707km VIN: AHTGA3DD600966785 License Plate: FZT446L

Customer Information

Name: MFC Dekra Nedbank Auction House Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01509

Version: V11.30 Repair Order Number: --

System Scanned(8)

System		Status/DTC
Engine and ECT		② 0
ABS/VSC/TRC		Q 4
SRS airbag		② 0
Combination meter		Q 1
Air conditioner		Q 1
Cruise control	ADAS	② 0
4WD		Q 2
Navigation system		Q 1

Material Description ■ DTC (9)

ABS/VSC/TRC (4 DTCs)

DTC	Description	Status
C1241	Low or high power supply voltage	History
C1407	Right rear speed sensor circuit open or short	Current
C1407	Right rear speed sensor circuit open or short	History
C1415	Right rear speed sensor circuit output	History
Combination meter (1 DTC)		

Description

D10	D C C C C C C C C C C C C C C C C C C C	Otatao
B150A	Lost communication with HMI-LAN	History

Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

4WD (2 DTCs)

AUTEL www.autel.com

MaxiSys MS906 BT

Status

/Toyota/Hilux	Test Time: 2025-06-05 11:13:40	Report ID: MAXIA20250605111340
DTC	Description	Status
P17BC	Rear differential lock position switch stuck in on position	n History
U0416	Invalid data received from vehicle dynamic control (VDC) module	History
Navigation sys	stem (1 DTC)	
DTC	Description	Status
U0100	Engine/EV ECU communication	History
Technician No	otes	

Technician Notes 2016903257

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2