



Shop: Dekra MFC Auction House
 Tel: --
 Email: --
 Address: MFC AUCTION HOUSE
 M57 PRETORIA ROAD
 KEMPTON PARK

Report ID: MAXIA20240815131448
 Test Time: 2024-08-15 13:14:48
 Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
 VIN: AHTSS22P207157340

Odometer Reading: 20574km
 License Plate: LB526MP

Customer Information

Name: Dekra MFC AUCTION HOUSE






Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V11.00

Serial Number: VB8GJCC01514
 Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 1
ABS/VSC/TRC	 0
SRS airbag	 2
Combination meter	 1
Immobilizer	 0

DTC (4)

Engine and ECT (1 DTC)

DTC	Description	Status
P0500	Vehicle speed sensor (VSS)	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

Technician Notes

2016493537

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.