

Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240711092322
Test Time: 2024-07-11 09:23:22
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P507149555
Odometer Reading: 84267km
License Plate: LF74ZHGP






Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.10
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 4
SRS airbag	 2
Combination meter	 0
Immobilizer	 0

DTC (6)

ABS/VSC/TRC (4 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1403	Fault in rear speed sensor right circuit	History
C1404	Fault in rear speed sensor left circuit	History
C1415	Right rear speed sensor circuit output	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History



Technician Notes

2016450460

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.