



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250828121433
Test Time: 2025-08-28 12:14:33
Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Accent(RB)/--
VIN: KMHCT41DLHU240223

Odometer Reading: 212837
License Plate: FR27YNGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.90

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ENG (Engine)	 3
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 2
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0

DTC (5)

ENG (Engine) (3 DTCs)

DTC	Description	Status
P0122	Throttle position sensor (TPS) 1 signal circuit input low	History
P0222	Throttle position sensor (TPS) 2 signal circuit input low	History
P0620	Alternator control circuit	Active

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102	Battery voltage low	History
B1346	Driver airbag (DAB) resistance too high (1st Stage)	Active

Technician Notes

2016994513



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.