

**Shop: --**Tel: --Email: --Address: -- Report ID: MAXIA20240306123954 Test Time: 2024-03-06 12:39:54 Technician: Andrick

## Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information		
/Hyundai/Accent(RB)/	Odometer Reading: 244087	
VIN: KMHCT41DLKU473793	License Plate: JJ95HFGP	
Customer Information		
Name: MFC Dekra Nedbank Auction House	Tel: 0861033572	
Device information		
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01509	
Version: V13.50	Repair Order Number:	

## System Scanned(7)

System	Status/DTC
ENG (Engine)	<b>Q</b> 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	3 2
AB (Airbag)	3
IMMO (Immobilizer)	<b>O</b>
CODE (Transmitter Code Saving)	<b>o</b>
EPS (Motor Driven Power Steering)	<b>Q</b> 1
BCM (Body Control)	<b>o</b>

## 🔼 DTC (7)

ENG	(Engine)	(1	DTC)	
-----	----------	----	------	--

DTC	Description	Status			
P0011	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	Pending			
ABS/ESP (Anti	ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)				
DTC	Description	Status			
C1201	Left front vehicle speed sensor (VSS) range/performance/Intermittent	History			
C1202	Left front vehicle speed sensor (VSS) invalid/No signal	History			
AB (Airbag) ( 3 DTCs )					
DTC	Description	Status			
B1102	Battery voltage low	History			
B1650	Crash recorded in 1st stage only (Frontal - Replace SRSCM)	Active			
AUTEL www	w.autel.com MaxiSys MS906 BT	Page 1			

Hyundai/ Accent(F	B)/	Test Time: 2024-03-06 12:39:54	Report ID: MAXIA20240306123954	
B2500	Warning lamp failure		History	
EPS (Motor Driven Power Steering) (1 DTC)				
DTC	Description		Status	
C1611	CAN Timeout - Engine management system (EMS)		History	
Technician Notes 2016295247				

Customer name:

Technician: \_\_\_\_\_

Date:

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.