

Shop: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20240724104914  
Test Time: 2024-07-24 10:49:14  
Technician: Sbu

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/Elantra(MD)/--  
VIN: KMHDH41CMFU462579

Odometer Reading: 314257  
License Plate: JX44SGGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE














Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.70

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 13 )

System	Status/DTC
ENG (Engine)	 4
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
SJB (Smart Junction Block)	 3
SVC (Service Reminder)	 0
CLU_VC (Cluster Variant Coding)	 0

## DTC ( 8 )

### ENG (Engine) ( 4 DTCs )

DTC	Description	Status
P0014	Exhaust camshaft position (CMP) B timing over-Advanced or system performance (Bank 1)	Pending



P0080	Exhaust valve control solenoid circuit high (Bank 1)	Pending
P0130	Oxygen sensor circuit (Bank 1 sensor 1)	Pending
P2188	System too rich at idle (Bank 1)	History

AB (Airbag) ( 1 DTC )

DTC	Description	Status
B1102:00	Battery voltage low	History

SJB (Smart Junction Block) ( 3 DTCs )

DTC	Description	Status
B2519	Left rear turn signal lamp circuit open	History
B2520	Right front turn signal lamp circuit open	History
B2521	Right rear turn signal lamp circuit open	History

Technician Notes

2016466181

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.