

Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE M57 PRETORIA ROAD **KEMPTON PARK**

Report ID: MAXIA20250812104103 Test Time: 2025-08-12 10:41:03

Technician: Andrick

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Haval Jolion/Fuel edition/--VIN: LGWEE4A51PK617146

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01514

Version: V11.00 Repair Order Number: --

🔀 System Scanned(14)	
System	Status/DTC
ECM (Engine Control Module)-ECM (Engine Control Module) - 4G15H&4G15K - UAES	O
ESP (Electronic Stability Program)	Q 1
SRS (Supplemental Restraint System)	Q 1
BCM (Body Control Module)-BCM (Body Control Module) - KOSTAL	Q 2
ICM/IP (Instrument Cluster Module/Instrument Pannel)-IP (Instrument Panel) - 7 Inches - Yazaki	② 0
TPMS (Tire Pressure Monitoring System)	Q 2
GW (Gateway)	② 0
APS (Automatic Parking System)	APAS N 11
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function	⊘ 0
EPS (Electric Power Steering)-EPS (Electric Power Steering) - Bosch	Q 1
ESCL (Electronic Steering Column Lock)	② 0
F-PBOX (Front Fuse Box Module)	Q 1
R-PBOX (Rear Fuse Box Module)	Q 1
RPAS (Rear Parking Assist System)	APAS N 11

.....

Odometer Reading: 25201

License Plate: LK76BHGP

Tel: 0861033572

TOTE (31)

ESP (Electronic Stability Program) (1 DTC)



MaxiSys MS906 BT

Page 1

/GreatWall/Hava	Il Jolion/Fuel edition Test Time: 2025-08-12 10:41:03	Report ID: MAXIA2025081210410
DTC	Description	Status
U016386	Vehicle speed signal invalid	History DTC
SRS (Supplem	ental Restraint System) (1 DTC)	
DTC	Description	Status
U110116	Diagnostic voltage too low	History DTC
BCM (Body Co	ontrol Module)-BCM (Body Control Module) - KOSTAL (2 DTCs)	
DTC	Description	Status
B185100	Ignition key battery low	Current DTC
B184300	ECSL verification failed	History DTC
ΓΡΜS (Tire Pr	essure Monitoring System) (2 DTCs)	
DTC	Description	Status
C007703	Right rear tire low pressure warning	Current DTC
U016387	Lost communication with HUT (navigation host system)	History DTC
APS (Automat	ic Parking System) (11 DTCs)	
DTC	Description	Status
U010087	Lost communication with ECM	History DTC
U012287	Lost communication with ESP(ABS)	History DTC
U100087	Lost communication with Air Bag Module (ABM)	History DTC
U100287	Lost communication with KBCM	History DTC
U016487	Lost communication with A/C (A/C-FCP)	History DTC
U110687	Lost communication with CSA	History DTC
U024587	Lost communication with navigation host system (HUT)	History DTC
U014687	Lost communication with gateway	History DTC
U012186	ESP(ABS) checksum error	History DTC
U012286	Electronic stability program checksum error	History DTC
U110116	Communication voltage too low	History DTC
EPS (Electric F	Power Steering)-EPS (Electric Power Steering) - Bosch (1 DTC)	
DTC	Description	Status
C141500	Power steering reduced due to voltage too low	Current DTC
-PBOX (Fron	t Fuse Box Module) (1 DTC)	
DTC	Description	Status
U110116	Communication voltage too low	Current DTC
R-PBOX (Rear	Fuse Box Module) (1 DTC)	
DTC	Description	Status
U110116	Communication voltage too low	Current DTC

Page 2 www.autel.com MaxiSys MS906 BT

RPAS (Rear Parking Assist System) (11 DTCs)

DTC	Description	Status
U010087	Lost communication with ECM	History DTC
U012287	Lost communication with ESP(ABS)	History DTC
U100087	Lost communication with Air Bag Module (ABM)	History DTC
U100287	Lost communication with KBCM	History DTC
U016487	Lost communication with A/C (A/C-FCP)	History DTC
U110687	Lost communication with CSA	History DTC
U024587	Lost communication with navigation host system (HUT)	History DTC
U014687	Lost communication with gateway	History DTC
U012186	Electronic stability program-ABS checksum error	History DTC
U012286	Electronic stability program checksum error	History DTC
U110116	ECU voltage too low	History DTC

Technician Notes 2016976331

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



www.autel.com MaxiSys MS906 BT Page 3