



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20250609125858
Test Time: 2025-06-09 12:58:58
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i10(PA)/--
VIN: MALAN51BLGM659407

Odometer Reading: 150736
License Plate: JW70VHGP

Customer Information

Name: MFC Dekra Nedbank Auction House





Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(4)

System	Status/DTC
ENG (Engine)	 2
AB (Airbag)	 1
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (3)

ENG (Engine) (2 DTCs)

DTC	Description	Status
P0131	Oxygen sensor circuit voltage low (Bank 1 sensor 1)	Pending
P0340	Intake camshaft position (CMP) sensor 'A' circuit (Bank 1 or single sensor)	History

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102	Battery voltage low	History

Technician Notes

2016906734

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

