

Peugeot VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Peugeot/3008/--

VIN: VF3M45GYVKS429372

Odometer Reading: 92926

License Plate: DuplooyGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V8.70

Repair Order Number: --



System Scanned(23)

System	Status/DTC
Built-in Systems Interface (BSI) -- BSI2010_EV	10
Automatic or piloted M/T -- BVA_AM6_AT6_UDS	1
A/T ECU -- COMELEC2	0
ABS or ESP -- ESP90	4
Airbags and pretensioners ECU -- RBG_SPEED_UDS	1
Combination instrument -- CIROCCO	0
Parking assist -- AAS_UDS	2
A/C -- BCC	0
Driver door module -- PDPC_UDS	4
Sequential gear lever -- ESM	0
Power steering -- DAE_BVH2	3
Battery State Of Charge (SOC) control unit -- BECB_GEN2	0
Controls under the steering wheel -- COM2008P	0
Steering wheel controls / Integral controls steering wheel -- VCI	0
Multi-function control panel -- FMUX	0
Seatbelt not fastened warning lamps unit -- TNB_2010	0
Front wiper -- ESV	1

Rain/Light Sensor (RLS) -- CDPL_UDS_HELLA

 0

Multi-function video camera (CMF) -- CVM_2

ADAS

 3

Touchscreen -- EMF_DGT_LVDS_BD

 1

Radio-navigation/telematic unit/connected Radio system -- RCC

 3

Anti-theft alarm -- MUS2

 0

Intrusion alarm siren -- SIR

 0 **DTC (33)****Built-in Systems Interface (BSI) -- BSI2010_EV (10 DTCs)**

DTC	Description	Status
U1F39:87	No communication with rain/light sensor	Intermittent
U1F57:87	No communication with the alarm ultrasound module	Intermittent
B181A:87	Fault in response from electric steering lock to request for locking/unlocking -- No reply	Intermittent
B1808:87	Fault in unlocking of immobilizer by engine ECU -- Request missing	Intermittent
B152B:11	Radio On/Off button fault -- Key locked Or Short circuit to ground	Intermittent
B2ED3:00	Loss of Built-in Systems Interface (BSI) time counter	Present
B117C:12	Fault in exterior lateral lighting control -- Short circuit to positive	Present
B1865:23	Inconsistency between status of engine starting switch and status of Built-in Systems Interface (BSI) engine starting authorization output	Intermittent
U1F05:12	Remote controlled triggering line fault -- Short circuit to positive	Intermittent
B1003:00	Configuration fault (Warning! This may be a phantom fault)	Intermittent

Automatic or piloted M/T -- BVA_AM6_AT6_UDS (1 DTC)

DTC	Description	Status
U1213:81	Communication fault on the CAN with the ESP ECU -- Value received incorrect	Permanent

ABS or ESP -- ESP90 (4 DTCs)

DTC	Description	Status
C156D:62	Electric Parking Brake (EPB) actuator sensors -- Inconsistency of signal	Intermittent

C154A:78	Left motorized brake caliper -- Abnormal stop, Incorrect back-up position on release	Intermittent
C1549:78	Right electric brake caliper -- Programing not performed	Intermittent
P0560:16	Electrical supply of ESP ECU -- Voltage below the threshold	Intermittent

Airbags and pretensioners ECU -- RBG_SPEED_UDS (1 DTC)

DTC	Description	Status
B1400:64	CAN+ supply voltage	Intermittent

Parking assist -- AAS_UDS (2 DTCs)

DTC	Description	Status
B1221:92	Fault in inner left front parking assistance sensor -- Operation or performance incorrect	Intermittent
B1222:92	Outer left front parking assist sensor fault -- Operation or performance incorrect	Intermittent

Driver door module -- PDPC_UDS (4 DTCs)

DTC	Description	Status
B1391:16	Fault in left front power window motor -- Supply voltage too low	Intermittent
B1392:16	Right front power window motor fault -- Supply voltage too low	Intermittent
B1393:16	Fault in left rear power window motor -- Supply voltage too low	Permanent
B1386:16	Right rear power window motor fault -- Supply voltage too low	Intermittent

Power steering -- DAE_BVH2 (3 DTCs)

DTC	Description	Status
C1406	Power steering motor or ECU overheating	Permanent fault
C1644	Supply fault -- Open circuit	Permanent fault
P0562	Undervoltage fault -- Not characterized	Permanent fault

Front wiper -- ESV (1 DTC)

DTC	Description	Status
B100C:16	Wipers ECU supply -- Voltage too low	Intermittent

Multi-function video camera (CMF) -- CVM_2 (3 DTCs)

DTC	Description	Status
U1218:29	Communication with the Built-in Systems Interface (BSI) - - Data received invalid	Intermittent

B100C:1C	Power supply for multi-function video camera -- Voltage out of range	Intermittent
U1F0A:01	CAN -- Not characterized	Intermittent

Touchscreen -- EMF_DGT_LVDS_BD (1 DTC)

DTC	Description	Status
U1FA0:00	Low Voltage Differential Signaling (LVDS) response time incorrect (Low Voltage Differential Signaling (LVDS))	Intermittent

Radio-navigation/telematic unit/connected Radio system -- RCC (3 DTCs)

DTC	Description	Status
B100C:00	RCC connected audio system electrical supply -- Not characterized	Intermittent
B1507:19	Antenna input 1 -- Excessive current	Intermittent
B1508:19	Antenna input 2 -- Excessive current	Intermittent

Technician Notes

2016318268

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.