AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240223094713 Test Time: 2024-02-23 09:47:13

**0** 

Page 1

Technician: Travino

## Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

**Vehicle Information** 

--/Mercedes-Benz/177.087 - A 200/--

VIN: WDD1770872J037983

**Customer Information** 

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

**Device information** 

Scanner: MaxiSys MS906 BT

🔁 System Scanned( 33 )

PTCU(Drivetrain Control Unit)

MaxiSys MS906 BT

JTEL www.autel.com

Version: V18.80

Odometer Reading: 40951 License Plate: KVT019MP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

System	Status/DTC
ECM(Engine Control Unit)	<b>②</b> 0
TCM(Transmission Control Unit)	<b>②</b> 0
ESP(Electronic Stability Program Braking System)	<b>②</b> 0
SRS(Supplemental Restraint System Control Unit)	<b>O</b>
KI(Instrument Cluster)	<b>②</b> 0
TPM(Tire Pressure Monitor Control Unit)	<b>O</b>
PTS(Parking System)	<b>◎</b> 0
SAM(Signal Acquisition Control Unit)	<b>◎</b> 0
LIN:AISP(Interior Rearview Mirror)	<b>◎</b> 0
LIN:BSN(Battery Sensor)	<b>O</b>
LIN:DBE-1(Sunroof Control Unit)	<b>②</b> 0
LIN:FSW(Wiper Motor)	<b>O</b>
LIN:SHM(Seat Heating/Ventilation)	<b>②</b> 0
LIN:VCS(Rain/Light Sensor)	<b>O</b>
EZS(Electronic Ignition Lock Control Unit)	<b>Q</b> 1
ES(Electric Power Steering)	<b>O</b>
KLA(Air Conditioner Control Unit)	<b>⊘</b> 0

/Mercedes-Benz/	177.087 - A 200 Test	t Time: 2024-02-23 09:47:13	Report ID: MAXIA20240223094713
HU(Head Uni	t Control Unit)		<b>⊘</b> 0
LRE(Steering	Wheel Electronics)		<b>②</b> 0
ABA(Front Ra	dar Sensor)	APAS	<b>Q</b> 2
DMFL(Left Fr	ont Door Control Unit)		<b>②</b> 0
LIN:DMRL(Le	ft Rear Door Control Unit)		<b>O</b>
DMFR(Right I	Front Door Control Unit)		<b>Q</b> 1
LIN:DMRR(Ri	ght Rear Door Control Unit)		<b>②</b> 0
TPAD(Touch	Head Unit Controller)		<b>⊘</b> 0
ZAN(Center D	risplay Control Unit)		<b>◎</b> 0
·	g Column Control Unit)		<b>⊘</b> 0
	ımp Control Unit)		<b>◎</b> 0
·	Protection System Control Unit)		<b>◎</b> 0
LIN:AS(Alarm			<b>○</b> 0
	·		
DTA(Telematics Service Control Unit)		<b>Q</b> 1	
`	t Lighting Lamp)		<b>②</b> 0
DTC (5)	Ignition Lock Control Unit) (1 DTC)		
DTC	Description		Status
U103E00	Communication with the suspe	ension FlexRay has a	Stored
ABA(Front Rad	ar Sensor) ( 2 DTCs )		
DTC	Description		Status
C174AFA	The calibration of 'Front Radar	Sensor' has a malfunction.	Active and stored
C174AFB	The calibration of 'Front Radar	Sensor' has a malfunction.	Active and stored
DMFR(Right Fr	ont Door Control Unit) (1 DTC)		
DTC	Description		Status
B1DD015	The output for the mirror heate is a short circuit to positive or a		Active and stored
DTA(Telematic	s Service Control Unit) (1 DTC)		
DTC	Description		Status

AUTEL www.autel.com MaxiSys MS906 BT Page 2

/Mercedes-Benz/177.087 - A 200	Test Time: 2024-02-23 09:47:13	Report ID: MAXIA20240223094713
--------------------------------	--------------------------------	--------------------------------

B129A00 The control unit for telematics services was shut off due to a crash signal.

Active and stored

**Technician Notes** 

2016278117

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 3