



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250701105522
Test Time: 2025-07-01 10:55:22
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: WVWZZZ6RZHY071232

Odometer Reading: 203062
License Plate: LGG289MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
01 - Engine Control Module 1	9
02 - Transmission electronics	2
03 - Brakes 1	1
15 - Airbag	2
17 - Instrument cluster	1
44 - Power Steering	1
55 - Headlight Regulation	0

DTC (16)

01 - Engine Control Module 1 (9 DTCs)

DTC	Description	Status
P212700	Throttle/pedal position sensor/switch E Circuit low input	Passive/Sporadic
P008900	Fuel Pressure Regulator 'A' Performance	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic
P164E00	Oil pressure regulation valve Electrical error	Active/static
P225100	O2 Sensor Negative Current Control Circuit Bank 1 Sensor 1 open	Passive/Sporadic
P11A600	Cylinder 2 cam adjuster A Range/performance	Passive/Sporadic



P11A400	Cylinder 1 cam adjuster B Range/performance	Passive/Sporadic
P11AC00	Cylinder 3 cam adjuster B Range/performance	Passive/Sporadic
P11A800	Cylinder 2 cam adjuster B Range/performance	Passive/Sporadic

02 - Transmission electronics (2 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
P056200	System Voltage Low Voltage	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
C10EE00	Fault detected in roll mode	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

Technician Notes
2016931041

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

