



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	23/05/2024		M57 Pretoria Road - 1619
Inspection Date	23/05/2024		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	MAZDA	Registration Number	HWB377MP
Model	MAZDA 3	Register Number	
VIN	JM6BL10F2C0309036	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/01/2025
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	271,029 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Repair
Fan Belt Worn	Replace
Engine Management Lights Set	Repair
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Gear Lever Dust Boot Damaged	Replace
Side Mirror Left Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Leak	Repair
Radiator Cradle Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BL10F2C0309036

1 / 13



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

Damage	Repair Way
Brakes Noisy	Replace
Engine Performance Idling / Hunting	Repair
Engine	aircon fan belt missing
interior	starter button damaged
interior	Vehicle interior in poor condition.
Engine	fan cowl damaged
Body and exterior	Signs of impact damage to front of vehicle.
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Poor alignment to somebody panels.
Body and exterior	Repair work done to vehicle below standard.
axle and suspension	excessive noise from front and rear suspension.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.51	2.9	-	
Rear	2.1	2.33	-	
Emergency / Parking	1.66	1.75	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/50R17	93W	Royalblack	Radial	V	2723	1 mm
Front Right	205/50R17	93W	Wanli	Radial	V	0321	0 mm
Rear Left	215/40R17	87V	Continental	Contipremium	V	4517	0 mm
Rear Right	215/50R17	91W	Goodride	Radial	V	3915	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


VIN: JM6B11052G0300026

Report No: 2016390243


2 / 13

DATE


23/05/2024



Brake and shock test



Diagnostics.



Diagnostics.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

**CONDITION REPORT****Report No: 2016390243**

VIN: JM6BL10F2C0309036

DATE**23/05/2024**

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
VIN: JM6BL10F2C0309036
23/05/2024
4 / 13



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE

23/05/2024

VIN: JM6BL10F2C0309036

5 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

VIN: JM6BL10F2C0309036


6 / 13




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

VIN: JM6BL10F2C0309036
7 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


Report No: 2016390243

DATE
23/05/2024

VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

VIN: JM6BL10F2C0309036
9 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

Fan Belt



Engine Wiring

VIN: JM6BL10F2C0309036

10 / 13



Engine Wiring



Headlight Left



Headlight Right



Front Bumper



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

VIN: JM6BL10F2C0309036
11 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024



Front Bumper



Bonnet

VIN: JM6BL10F2C0309036
12 / 13



Front Fender Left



Door Front Left



Side Mirror Left



Door Rear Left



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

VIN: JM6BL10F2C0309036
13 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

Rear Fender Left




Rear bumper



Rear bumper



Boot Lid / Hatch door



Front Fender Right



Rear Fender Right



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024


Door Front Right




Door Rear Right



Windscreen



Seat Front Right



Seat Front Left



Gear Lever Dust Boot



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


Report No: 2016390243

DATE
23/05/2024

Engine Management Lights



Tail Light Right



Tyre Rear Left



Tyre Rear Right



Tyre Front Right



Engine



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016390243

DATE
23/05/2024

Gearbox



Radiator Cradle

**CONDITION REPORT****Report No: 2016390243****DATE**
23/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za