



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 24/04/2024        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 24/04/2024        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                   |                         |                   |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        | MFC AUCTION HOUSE |
| Manufacturer    | MAZDA             | Registration Number     | JH82BKGP          |
| Model           | MAZDA 3           | Register Number         |                   |
| VIN             | JM6BL10Z2C0305004 | Date Of First Licensing |                   |
| Engine Number   |                   | Last COR                |                   |
| Doors           | 5                 | License Expiry Date     | 24/04/2024        |
| Color           | WHITE             | Power / Displacement    |                   |
| Year Model      |                   | Paint Finish            | PEARL EFFECT      |
| Km Reading      | 222,391 KM        | Fuel                    | PETROL            |
| Cab / Body Type | HATCHBACK         | Transmission            | MANUAL            |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

| Damage                                      | Repair Way |
|---------------------------------------------|------------|
| Engine Oil Leak                             | Repair     |
| Under bonnet insulation cover Damaged       | Repair     |
| Windscreen Wiper Damaged                    | Replace    |
| Air Conditioner Insufficient                | Replace    |
| Tail Light Left Cracked                     | Replace    |
| Bright Light Right Damaged                  | Replace    |
| Headlight Left Defective                    | Repair     |
| Headlight Right Damaged                     | Repair     |
| Seat Front Left Dirty                       | Repair     |
| Seat Rear Defective                         | Repair     |
| Steering Wheel Trim Defective               | Repair     |
| Side Mirror Left Damaged                    | Repair     |
| Front Bumper Damaged                        | Repair     |
| Bonnet Residual Traces of Repair            | Repair     |
| C • Pillar Left Residual Traces of Repair   | Repair     |
| Front Fender Left Paintwork • Scratched     | Repair     |
| Front Fender Right Dented                   | Repair     |
| Rear Fender Left Residual Traces of Repair  | Repair     |
| Rear Fender Right / Inner Tray Dented       | Repair     |
| Door Front Left Residual Traces of Repair   | Repair     |
| Door Front Right Dented                     | Repair     |
| Door Rear Left Residual Traces of Repair    | Repair     |
| Door Rear Right Paintwork • Scratched       | Repair     |
| Boot Lid / Hatch door Paintwork • Chipmarks | Repair     |
| Rear bumper Paintwork • Scratched           | Repair     |
| Windscreen Chipped                          | Replace    |
| Rim Front Left Dented                       | Repair     |
| Rim Front Right Scratched                   | Repair     |
| Rim Rear Left Defective                     | Repair     |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: JM6BL10Z2C0305004

1 / 15



## CONDITION REPORT

Report No: 2016353244

 DATE  
24/04/2024

| Damage                                 | Repair Way                                       |
|----------------------------------------|--------------------------------------------------|
| Rim Rear Right Defective               | Repair                                           |
| Chassis Dented                         | Repair                                           |
| Sub Frame Scratched                    | Repair                                           |
| Engine to silencer pipe Welded         | Replace                                          |
| Belly plates Defective                 | Repair                                           |
| Gearbox Oil Leak                       | Repair                                           |
| Steering Malfunction                   | Repair                                           |
| Engine Noise Excessive                 | Repair                                           |
| Warning light illuminated on dashboard | Repair                                           |
| Interior                               | Vehicle interior dirty and some panels scratched |
| Body and Exterior                      | Vehicle license disk missing                     |
| Engine                                 | Engine bay dirty                                 |
| Undercarriage                          | Vehicle undercarriage dirty                      |
| Undercarriage                          | Bottom of engine and gearbox covered             |
| Body and Exterior                      | Dents and scratches on some body panels          |
| Body and Exterior                      | Residual traces of repair on some body panels    |
| Body and Exterior                      | Stone chips and spray work on some body panels   |
| Body and Exterior                      | Some body panels misaligned                      |
| Electrical instruments and components  | Vehicle electronics malfunctioning               |
| Axle and suspension                    | Front and rear suspension noisy                  |
| Undercarriage                          | Signs of surface rust on undercarriage           |

### Brakes

#### Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 2.5                | 2.73               | -                |                                  |
| Rear                | 1.63               | 1.65               | -                |                                  |
| Emergency / Parking | 1.37               | 1.57               | -                |                                  |

### Tyres and Rims

#### Tyre Specification & Measurement

|             | Size        | Load/Speed Index | Manufacture | Model     | Type* | Production Date | Tread Depth (mm) |
|-------------|-------------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left  | 225/45 R17  | 94W              | Dunlop      | Sp-Sport  | V     | 3421            | 2 mm             |
| Front Right | 225/45 R17  | 91W              | Dunlop      | Sp-Sport  | V     | 4321            | 4 mm             |
| Rear Left   | 225/45 R17  | 94W              | Dunlop      | Sp-Sport  | V     | 4321            | 6 mm             |
| Rear Right  | 225/45 R17  | 94W              | Dunlop      | Sp-Sport  | V     | 2321            | 4 mm             |
| Spare       | T115/70 D15 | 90M              | Toyo        | Temporary | V     | 3111            | 3 mm             |

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System                         | Code        | Description                                      | Status |
|----|--------------------------------|-------------|--------------------------------------------------|--------|
| 1  | PCM(POWERTRAIN CONTROL MODULE) | P0328:00-AC | KNOCK/COMBUSTION VIBRATION SENSOR A CIRCUIT HIGH |        |

### Inspection Conditions

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za



## CONDITION REPORT

Vehicle No: 201635244

Report No: 201635244

2 / 15

DATE

24/04/2024

**Technician**

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



## CONDITION REPORT

Report No: 2016353244

VIN: JM6BL10Z2C0305004

DATE  
3 / 15  
24/04/2024

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report page 1

|                                                         |                               |                               |
|---------------------------------------------------------|-------------------------------|-------------------------------|
| Model: AN118 / PAU2431                                  | Test Item: 1014-09-30-1000-14 | Report ID: 866040E240C4001218 |
| <b>Technician Notes</b>                                 |                               |                               |
| 2016033014                                              |                               |                               |
| Customer name: _____                                    |                               |                               |
| Technician: _____                                       |                               |                               |
| Date: _____                                             |                               |                               |
| *One Please scan a copy of this report to your records. |                               |                               |

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



CONDITION REPORT

Report No: 2016353244

VIN: JM6BL10Z2C0373024  
DATE: 24/04/2024  
4 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

VIN: JM6BL10Z2C0305004

5 / 15



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

VIN: JM6BL10Z2C0305004

6 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

VIN: JM6BL10Z2C0305004  
8 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Spare wheel Accessories




LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

**CONDITION REPORT****Report No: 2016353244****DATE**  
**24/04/2024**

VIN: JM6BL10Z2C0305004

10 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Oil cap and dipstick



Seat Rear

VIN: JM6BL02C0305004

11 / 15



Seat Rear



Seat Front Left



Windscreen Wiper



Side Mirror Left



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

VIN: JM6BL10Z2C0305004

12 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024



Front Bumper



Front Bumper

2C0305004  
13 / 15



Bonnet



Headlight Left



Headlight Right



Windscreen

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

VIN: JM6BL10Z2C0305004

14 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Water level



15 / 15

Engine



Headlight Right



Bright Light Right



Front Fender Right



Rim Front Right



CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Rim Rear Right



Rim Rear Left



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024


Rim Front Left



Door Rear Right



Door Front Right



Rim Front Left



Gearbox



Engine



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Sub Frame



Belly plates



Belly plates



Rear Fender Right / Inner Tray



Engine to silencer pipe



Belly plates



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Chassis



Under bonnet insulation cover



C • Pillar Left



Tail Light Left



Boot Lid / Hatch door



Rear bumper



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016353244

DATE  
24/04/2024

Rear bumper



Windscreen Wiper



Steering Wheel Trim



Air Conditioner

**CONDITION REPORT****Report No: 2016353244****DATE**  
**24/04/2024**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za