



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 06/02/2024 | | M57 Pretoria Road - 1619 |
| Inspection Date | 06/02/2024 | | Kempton Park - GT |

Vehicle Data


| | | | |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | CHEVROLET | Registration Number | JXB681MP |
| Model | CAPTIVE | Register Number | |
| VIN | KL1FC6EC8BB075423 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 30/09/2020 |
| Color | WHITE | Power / Displacement | |
| Year Model | | Paint Finish | C - COMMON |
| Km Reading | 149,715 KM | Fuel | PETROL |
| Cab / Body Type | STATION WAGON | Transmission | AUTOMATIC |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

| Damage | Repair Way |
|--|------------|
| Engine Oil Leak | Repair |
| Caps Defective | Replace |
| Indicator Light Front Right Broken | Replace |
| Door Handle Rear Right Damaged | Replace |
| Boot Lid / Hatch door Dented | Repair |
| Brake disc 1. Axle right Excessive Wear & Tear | Replace |
| Ball Joint(s) Front Axle Right Cracked | Replace |
| Clutch Operation Shudder | Repair |
| Engine warning light illuminated. | Repair |



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KL1FC6EC8BB075423



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

Brakes

Brake Test Results

| | Left | Right | Axle Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | - | - | - | - |
| Rear | - | - | - | - |
| Emergency / Parking | - | - | - | - |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left | 235/50R19 | 103W | Ling long | Crosswind | V | 5220 | 5 mm |
| Front Right | 235/50R19 | 103W | Radar | Dimax | V | 0000 | 6 mm |
| Rear Left | 235/50R19 | 99V | Goodyear | Eagle | V | 0421 | 1 mm |
| Rear Right | 235/50R19 | 99V | Goodyear | Eagle | V | 0421 | 5 mm |
| Spare | 215/70R16 | 100T | Hankook | Dynamic | V | /////// | 5 mm |

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Electrical Components and Instruments: Electronics malfunction. R/F electric mirror malfunction. Wiper bl

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016256538


2 / 9

DATE


06/02/2024




Shock test



Diagnostic test



Diagnostic test



Diagnostic



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558
VIN: KL1FC6EC8BB075423
DATE
3/6
06/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE: 08/02/2024
VIN: KL1FC6EG080002024
4/9



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

VIN: KL1FC6EC8BB075423

5 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

VIN: KL1FC6EC8BB075423

6 / 9



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

VIN: KL1FC6EC8BB075423

7 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

VIN: KL1FC6EC8BB075423

9 / 9



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024



Door Handle Rear Right



Water level



Caps



Caps



Indicator Light Front Right



Brake disc 1. Axle right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024



Engine



Engine



Engine



Engine



Ball Joint(s) Front Axle Right



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016256558

DATE
06/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za