

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	02/07/2024		M57 Pretoria Road - 1619
Inspection Date	02/07/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	KIA	Registration Number	JV91HRGP
Model	RIO	Register Number	
VIN	KNADB514LM6493345	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/03/2025
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	83,374 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Central Air Vent Defective	Repair
Headlight Left Defective	Repair
Hood Lining Dirty	Repair
Door Panel Rear Left Defective	Repair
Door Sealing Rubber Front Left Torn / Cut	Replace
Door Sealing Rubber Front Right Damaged	Replace
Boot Panel Left Defective	Repair
Boot Panel Right Defective	Repair
Steering Wheel Trim Defective	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Rocker Panel Left Defective	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Tyre Front Right Defective	Replace
Tyre Rear Right Defective	Replace
Rim Front Left Scratched	Repair
Rim Rear Left Scratched	Repair

Damage	Repair Way
Chassis Damaged	Repair
Belly plates Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Defective	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Gearbox Oil Sweat	Repair
Triangle Damaged	Replace
Engine	Signs of rodent in engine bay
Engine	Engine bay dirty
Undercarriage	Vehicle undercarriage dirty
Undercarriage	Bottom of engine and gearbox covered
Body and Exterior	Dents and scratches on some body panels
Interior	Vehicle interior dirty and some panels scratched
Body and Exterior	Signs of hail damage on some body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.9	1.91	-	
Rear	2.17	2.08	-	
Emergency / Parking	1.42	1.34	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Nexen	Nblue	V	1220	1 mm
Front Right	185/65 R15	88H	Nexen	Nblue	V	1420	3 mm
Rear Left	185/65 R15	88T	Continental	ContiEco	V	3109	4 mm
Rear Right	185/65 R15	88H	Champro	GT Radial	V	2521	5 mm
Spare	T125/80 D15	95M	Maxxis	Temporary	V	1420	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0638:00	THROTTLE ACTUATOR CONTROL RANGE/PERFORMANCE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or



CONDITION REPORT

VIN: KNADRE141M6403345

Report No: 2016439572

2 / 14

DATE

02/07/2024

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Front chassis



Rear chassis

Vehicle Information			
Make/Model	Can	Year	2016
Engine No.	10718012	Engine Type	1.8L
Transmission	5-Speed	Drivetrain	FWD
Test Date	02/07/2024	Test Location	DEKRA
Brake and Shock Absorber Test Results			
Test	Left	Right	Pass/Fail
Shock Absorber	1.20	1.15	Pass
Brake Pad	1.20	1.15	Pass
Brake Disc	1.20	1.15	Pass
Brake Fluid	1.20	1.15	Pass

Brake and shock absorber report

Diagnostic Report	
Vehicle ID	KNADB514LM6493345
Test Date	02/07/2024
Test Location	DEKRA
Diagnostic Results	
Engine	Pass
Transmission	Pass
Drivetrain	Pass
Brake	Pass
Shock Absorber	Pass
Brake Fluid	Pass
Brake Pad	Pass
Brake Disc	Pass
Brake Light	Pass
Brake Master Cylinder	Pass
Brake Slave Cylinder	Pass
Brake Hose	Pass
Brake Line	Pass
Brake Bleeder Valve	Pass
Brake Adjuster	Pass
Brake Pedal	Pass
Brake Warning Light	Pass
Brake System	Pass

Diagnostic report page 1

Diagnostic Report			
Vehicle ID	KNADB514LM6493345	Test Date	02/07/2024
Test Location	DEKRA	Test Technician	DEKRA
Diagnostic Results			
Engine	Pass	Transmission	Pass
Drivetrain	Pass	Brake	Pass
Shock Absorber	Pass	Brake Fluid	Pass
Brake Pad	Pass	Brake Disc	Pass
Brake Light	Pass	Brake Master Cylinder	Pass
Brake Slave Cylinder	Pass	Brake Hose	Pass
Brake Line	Pass	Brake Bleeder Valve	Pass
Brake Adjuster	Pass	Brake Pedal	Pass
Brake Warning Light	Pass	Brake System	Pass

Diagnostic report page 2



Spare wheel and Accessories



Oil cap and dipstick



Manual transmission



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

VIN: KNAD8514LM6493345

7 / 14



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

VIN: KNADB514LM6493345

8 / 14



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

VIN: KNADB514LM6493345

10 / 14



Bonnet



Front Bumper

VIN: KNADB52LM6493345
11 / 14

Front Bumper



Headlight Left



Roof



Windscreen

VIN: KNADB514LM6493345

12 / 14



Hood Lining




Steering Wheel Trim



Central Air Vent



Central Air Vent



Door Sealing Rubber Front Right



Rear Fender Right

VIN: KNADB514LM6493345

14 / 14



Door Rear Right



Door Front Right



Side Mirror Right



Front Fender Right



Front Fender Left



Side Mirror Left




Door Front Left



Door Rear Left



Rear Fender Left



Door Sealing Rubber Front Left



Door Panel Rear Left



Rear bumper



Rear bumper



Triangle



Boot Panel Left



Boot Panel Right



Water level



Tyre Front Right



Rim Rear Left



Rocker Panel Left



Rim Front Left



Belly plates



CV Joint(s) Boot(s) Front Left (inner/outer)



Gearbox




CV Joint(s) Boot(s) Front Right (inner/outer)



Chassis



Tyre Rear Right



Water level



CONDITION REPORT

Report No: 2016439572

DATE
02/07/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za