



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 04/09/2025 | | M57 Pretoria Road - 1619 |
| Inspection Date | 04/09/2025 | | Kempton Park - |

Vehicle Data

| | | | |
|-----------------|----------------------------|-------------------------|--------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC |
| Manufacturer | KIA | Registration Number | FS90MHGP |
| Model | RIO 1.4 TEC AT [2015-2017] | Register Number | |
| VIN | KNADN412MG6623490 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 4 | License Expiry Date | |
| Color | GREY | Power / Displacement | |
| Year Model | 2017 | Paint Finish | M - METALLIC |
| Km Reading | 260,584 KM | Fuel | PETROL |
| Cab / Body Type | SEDAN | Transmission | AUTOMATIC |

Vehicle Options & Accessories**Items****VEHICLE INSPECTION**

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



| Damage | Repair Way |
|---|--|
| Indicator Light Front Right Cracked | Replace |
| Tail Light Right Broken | Replace |
| Number Plate Light Left Missing | Replace |
| Seat Front Right Torn / Cut | Repair |
| Rear Upper Valance Damaged | Repair |
| Front Bumper Paintwork • Scratched | Repair |
| Bonnet Paintwork • Dull | Repair |
| Rear Fender Left Paintwork • Scratched | Repair |
| Rear Fender Right Residual Traces of Repair | Repair |
| Door Rear Left Paintwork • Dull | Repair |
| Boot Lid / Hatch door Residual Traces of Repair | Repair |
| Rear bumper Residual Traces of Repair | Repair |
| Sill Panel Left Paintwork • Scratched | Repair |
| Sill Panel Right Paintwork • Scratched | Repair |
| Split Pin Left Missing | Replace |
| Split Pin Right Missing | Replace |
| Front suspension excessive noise | Repair |
| Body exterior | Minor dents scratches stone chips on some body pan |
| Body exterior | Signs of spray work done on some body panels |

Brakes

Brake Test Results

| | Left | Right | Axle Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [kN] | Braking Force [kN] | | |
| Front | 1.5 | 2.8 | - | |
| Rear | 1.5 | 1.9 | - | |
| Emergency / Parking | 1.1 | 1.9 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|-------|-------|-----------------|------------------|
| Front Left | 205/40R17 | 84W | Nexen | Nfera | V | 0224 | 5 mm |
| Front Right | 205/40R17 | 84W | Nexen | Nfera | V | 4424 | 6 mm |
| Rear Left | 205/40R17 | 84W | Nexen | Nfera | V | 0224 | 3 mm |
| Rear Right | 205/40R17 | 84W | Nexen | Nfera | V | 4424 | 3 mm |
| Spare | 205/40R17 | 84W | Nexen | Nfera | V | | 6 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|----|--------|-------|--|--------|
| 1 | ABS | C1209 | RIGHT REAR VEHICLE SPEED SENSOR VSS CIRCUIT OPEN O | |

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490




CONDITION REPORT




Report No:
2017002557
DATE
04/09/2025




Automatic



Shock and brake report



Diagnostic test



Diagnostic test



Sparewheel



Coolant

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



Oil cap and dipstick



Rear end



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



CHASSIS

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksdorp, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



ENGINE 2



ENGINE 1



Seat Front Right



Indicator Light Front Right



Rear Fender Right



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



Boot Lid / Hatch door



Tail Light Right



Rear Upper Valance



Rear Upper Valance



Rear Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



Door Rear Left



Bonnet



Front Bumper



Front Bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



Rear bumper



Rear bumper



Sill Panel Right



Split Pin Left



Split Pin Right



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490



CONDITION REPORT



Report No:
2017002557
DATE
04/09/2025



Sill Panel Left



Rear bumper



Rear bumper



Number Plate Light Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN412MG6623490