



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	10/01/2024		M57 Pretoria Road - 1619
Inspection Date	10/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	KIA	Registration Number	FP30KZGP
Model	RIO	Register Number	
VIN	KNADN511LG6021332	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2022
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	255,451 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Dim Light Left Defective	Repair
Dim Light Right Defective	Repair
Side Mirror Left Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Front Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Windscreen Cracked	Replace
Rim Front Left Dented	Repair
Rim Front Right Dented	Repair
Rim Rear Left Dented	Repair
Rim Rear Right Dented	Repair
Engine Noise Idling / Hunting	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNADN511LG6021332

1 / 13



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s²]
	Braking Force [KN]	Braking Force [KN]		
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Davanti	DX390	V	2123	5 mm
Front Right	185/65R15	88H	Davanti	DX390	V	2123	2 mm
Rear Left	185/65R15	88H	Davanti	DX390	V	2123	5 mm
Rear Right	185/65R15	88H	Davanti	DX390	V	2123	5 mm
Spare	185/65R15	92T	Barum	Brilliantis	V	////////	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents scratches and stone chips on some body panels.Signs of spray work done on

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius


This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT


VIN: KNADN51016025346
Report No: 2016225346
2 / 13
DATE
10/01/2024



Shock and brake report



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346
VIN: KNADN511LG6021332
DATE
3/13
10/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
VIN: KNADN511G000224
10/01/2024
4/13



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

VIN: KNADN511LG6021332

5 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346


DATE
10/01/2024

VIN: KNADN511LG6021332

6 / 13



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

VIN: KNADN511LG6021332
7 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024





CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

VIN: KNADN511LG6021332
9 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

R/F fender liner missing



L/F fender liner missing



R/R reflector broken



Coolant reservoir



Oil cap and dipstick



Manual



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

VIN: KNADN511LG6021332
11 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

Door Front Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Bumper



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

VIN: KNADN511LG6021332
13 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

Front Bumper



Front Bumper



Side Mirror Left



Door Front Left



Door Rear Left



Sill Panel Left



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

Sill Panel Left



Rear bumper



Rear bumper



Rear bumper



Door Rear Right



Rim Front Right



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

Engine



Rim Front Left



Rim Rear Left



Rim Rear Right



Dim Light Left



Dim Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

**CONDITION REPORT**

Report No: 2016223346

DATE
10/01/2024

Windscreen



CONDITION REPORT

Report No: 2016223346

DATE
10/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za