



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	19/06/2025		M57 Pretoria Road - 1619
Inspection Date	19/06/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	HG17DTGP
Model	FIGO 1.5 AMBIENTE [2015-2018]	Register Number	
VIN	MAJFXXMTKFKH80771	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/04/2025
Color	SILVER	Power / Displacement	
Year Model	2018	Paint Finish	M - METALLIC
Km Reading	335,769 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MAJFXXMTKFKH80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Damage

Repair Way

Engine Wiring Defective	Repair
Air cleaner Damaged	Repair
Central Air Vent Damaged	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Repair
Seat Front Right Torn / Cut	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Cracked	Replace
Front Bumper Damaged	Replace
Bonnet Paintwork • Flaking	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Dented	Repair
Windscreen Cracked	Replace
Tie Rod End right Damaged	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Engine to silencer pipe Welded	Repair
Radiator Cradle Damaged	Replace
Battery loose	Repair
Radiator loose	Repair
Engine light on	Repair
Both front fender liner damage	Replace
Bonnet not closing properly	Repair
Rear tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.9	2.3	-	
Rear	2.0	1.9	-	
Emergency / Parking	0.8	0.7	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFKH80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R14	86H	Good ride	Radial Rp28	V	0321	2 mm
Front Right	185/65R14	86H	Goodyear	Duragrip	V	4317	2 mm
Rear Left	165/80R14	85T	Apollo	Amazer	V	3618	2 mm
Rear Right	175/65R14	82T	Continental	Contact	V	4219	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CMDTCS	C1B00:62-0A	STEERING ANGEL SENSOR	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFHK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025

Car				Car			
Year/Chassis	2015/15118	Year/Chassis	2015/15118	Year/Chassis	2015/15118	Year/Chassis	2015/15118
Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771
Engine	1.6L	Engine	1.6L	Engine	1.6L	Engine	1.6L
Power	105 kW	Power	105 kW	Power	105 kW	Power	105 kW
Transmission	Manual	Transmission	Manual	Transmission	Manual	Transmission	Manual
Drive	Front	Drive	Front	Drive	Front	Drive	Front
Weight	1400 kg	Weight	1400 kg	Weight	1400 kg	Weight	1400 kg
Max speed	180 km/h	Max speed	180 km/h	Max speed	180 km/h	Max speed	180 km/h
0-100	11.5 sec	0-100	11.5 sec	0-100	11.5 sec	0-100	11.5 sec
Brake	300 mm	Brake	300 mm	Brake	300 mm	Brake	300 mm
Shock absorber	coil over	Shock absorber	coil over	Shock absorber	coil over	Shock absorber	coil over
Wheel	15"	Wheel	15"	Wheel	15"	Wheel	15"
Tire	185/65 R15	Tire	185/65 R15	Tire	185/65 R15	Tire	185/65 R15
Steering	rack and pinion	Steering	rack and pinion	Steering	rack and pinion	Steering	rack and pinion
Seat	4	Seat	4	Seat	4	Seat	4
Color	White	Color	White	Color	White	Color	White
Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771

Shock and brake report

Car				Car			
Year/Chassis	2015/15118	Year/Chassis	2015/15118	Year/Chassis	2015/15118	Year/Chassis	2015/15118
Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771
Engine	1.6L	Engine	1.6L	Engine	1.6L	Engine	1.6L
Power	105 kW	Power	105 kW	Power	105 kW	Power	105 kW
Transmission	Manual	Transmission	Manual	Transmission	Manual	Transmission	Manual
Drive	Front	Drive	Front	Drive	Front	Drive	Front
Weight	1400 kg	Weight	1400 kg	Weight	1400 kg	Weight	1400 kg
Max speed	180 km/h	Max speed	180 km/h	Max speed	180 km/h	Max speed	180 km/h
0-100	11.5 sec	0-100	11.5 sec	0-100	11.5 sec	0-100	11.5 sec
Brake	300 mm	Brake	300 mm	Brake	300 mm	Brake	300 mm
Shock absorber	coil over	Shock absorber	coil over	Shock absorber	coil over	Shock absorber	coil over
Wheel	15"	Wheel	15"	Wheel	15"	Wheel	15"
Tire	185/65 R15	Tire	185/65 R15	Tire	185/65 R15	Tire	185/65 R15
Steering	rack and pinion	Steering	rack and pinion	Steering	rack and pinion	Steering	rack and pinion
Seat	4	Seat	4	Seat	4	Seat	4
Color	White	Color	White	Color	White	Color	White
Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771

Diagnostic report

Car				Car			
Year/Chassis	2015/15118	Year/Chassis	2015/15118	Year/Chassis	2015/15118	Year/Chassis	2015/15118
Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771	Model	MAJXXMTKFKH80771
Engine	1.6L	Engine	1.6L	Engine	1.6L	Engine	1.6L
Power	105 kW	Power	105 kW	Power	105 kW	Power	105 kW
Transmission	Manual	Transmission	Manual	Transmission	Manual	Transmission	Manual
Drive	Front	Drive	Front	Drive	Front	Drive	Front
Weight	1400 kg	Weight	1400 kg	Weight	1400 kg	Weight	1400 kg
Max speed	180 km/h	Max speed	180 km/h	Max speed	180 km/h	Max speed	180 km/h
0-100	11.5 sec	0-100	11.5 sec	0-100	11.5 sec	0-100	11.5 sec
Brake	300 mm	Brake	300 mm	Brake	300 mm	Brake	300 mm
Shock absorber	coil over	Shock absorber	coil over	Shock absorber	coil over	Shock absorber	coil over
Wheel	15"	Wheel	15"	Wheel	15"	Wheel	15"
Tire	185/65 R15	Tire	185/65 R15	Tire	185/65 R15	Tire	185/65 R15
Steering	rack and pinion	Steering	rack and pinion	Steering	rack and pinion	Steering	rack and pinion
Seat	4	Seat	4	Seat	4	Seat	4
Color	White	Color	White	Color	White	Color	White
Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771	Registration	MAJXXMTKFKH80771

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJXXMTKFKH80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER




Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



90 DEGREE LEFT



LR TYRE TREAD



LF TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare rim no tire

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Expection bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFHK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Battery loose



Oil cap and dipstick



Water level



Engine Wiring



Air cleaner



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT




Report No:
2016917663
DATE
19/06/2025



Headlight Left




Bonnet



Windscreen



Central Air Vent



Seat Front Right



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Tail Light Right



Rear bumper



Rear bumper



Side Mirror Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Side Mirror Left



Door Rear Left



Sill Panel Left



Rear Fender Left



Boot Lid / Hatch door



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Front Wheel Left



Bolt(s) / Nut(s) Rear Wheel Left



Tie Rod End right



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771



CONDITION REPORT



Report No:
2016917663
DATE
19/06/2025



Engine to silencer pipe



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJFXXMTKFK80771