



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	17/01/2024		M57 Pretoria Road - 1619
Inspection Date	17/01/2024		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	HJ97VWGP
Model	GRAND I10	Register Number	
VIN	MALA851AMJM771836	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/08/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	154,564 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Dim Light Left Defective	Repair
Fog Light Front Left Defective	Repair
Fog Light Front Right Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Roof Dented	Repair
Gearbox Oil Leak	Repair
Radiator Cradle Damaged	Replace



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

Brakes

Brake Test Results

	Left	Right		
	Braking Force [kN]	Braking Force [kN]	Axle Weight [kg]	Deceleration [m/s ²]
Front	2.3	2.4	-	
Rear	1.5	1.6	-	
Emergency / Parking	1.2	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/65R14	79T	Fullrun	Frun one	V	0121	1 mm
Front Right	165/65R14	79T	Fullrun	Frun one	V	0121	1 mm
Rear Left	165/65R14	79T	Fullrun	Frun one	V	0121	5 mm
Rear Right	165/65R14	79T	Fullrun	Frun one	V		0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents scratches and stone chips on some body panels. Signs of spray work done on

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT


VIN: MAJAN1A2016231916

Report No: 2016231916


2 / 8

DATE


17/01/2024



Shock and brake report



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016231716

VIN: MALA851AMJM771836

DATE

17/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016231716

DATE

VIN: MALA851A1170172024

4 / 8



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

VIN: MALA851AMJM771836

5 / 8

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

VIN: MALA851AMJM771836

6 / 8



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No sparewheel



LICENSE DISC





CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

VIN: MALA851AMJM771836

7 / 8

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 201623176

DATE
17/01/2024

VIN PLATE OR STICKER



8 / 8

ENGINE 1



CHASSIS



ENGINE 2



Rear end



Coolant reservoir



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

Automatic



Oil cap and dipstick



Front Bumper



Gearbox



Radiator Cradle



Roof



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

Roof



Dim Light Left



Fog Light Front Left



Fog Light Front Right



CONDITION REPORT

Report No: 2016231716

DATE
17/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za