



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 01/03/2024 | | M57 Pretoria Road - 1619 |
| Inspection Date | 01/03/2024 | | Kempton Park - GT |

Vehicle Data

| | | | |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | HYUNDAI | Registration Number | FG67RCGP |
| Model | GRAND I10 | Register Number | |
| VIN | MALA851CLGM388073 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 31/07/2023 |
| Color | GREY | Power / Displacement | |
| Year Model | | Paint Finish | TWO COAT UNI |
| Km Reading | 170,207 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

| Damage | Repair Way |
|---|------------|
| Engine Oil Leak | Repair |
| Engine Wiring Defective | Replace |
| Hoses Water Leak | Repair |
| Radiator Defective | Repair |
| Battery box Corrosion | Repair |
| Air conditioner pipes Defective | Repair |
| Air cleaner Damaged | Replace |
| Hooter Defective | Repair |
| Heater control Defective | Replace |
| Switch Electrical Window Winder front left Defective | Repair |
| Switch Electrical Window Winder front right Defective | Repair |
| Windscreen Wiper Damaged | Replace |
| Park Light Front Left Malfunction | Replace |
| Park Light Front Right Damaged | Replace |
| Park Light Rear Left Defective | Repair |
| Tail Light Left Damaged | Replace |
| Tail Light Right Defective | Replace |
| Dim Light Left Damaged | Replace |
| Dim Light Right Damaged | Replace |
| Bright Light Right Damaged | Replace |
| Bright Light Left Damaged | Replace |
| Fog Light Front Left Damaged | Replace |
| Fog Light Front Right Damaged | Replace |
| Number Plate Light Left Defective | Replace |
| Number Plate Light Right Defective | Replace |
| Headlight Left Defective | Replace |
| Headlight Right Defective | Replace |
| Seat Front Left Dirty | Repair |
| Seat Front Right Damaged | Repair |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388073

1 / 32



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

| Damage | Repair Way |
|---|------------|
| Seat Rear Damaged | Repair |
| Seat Belt Front Right Damaged | Replace |
| Seat Belt Rear Left Damaged | Replace |
| Hood Lining Dirty | Repair |
| Door Panel Front Left Defective | Repair |
| Door Panel Front Right Defective | Replace |
| Door Panel Rear Left Defective | Repair |
| Door Panel Rear Right Defective | Repair |
| Door Sealing Rubber Front Left Damaged | Replace |
| Door Sealing Rubber Front Right Damaged | Replace |
| Door Sealing Rubber Rear Left Missing | Replace |
| Door Sealing Rubber Rear Right Damaged | Replace |
| Door Lock Front Left Defective | Replace |
| Parcel Tray Damaged | Repair |
| Dash Padding Defective | Repair |
| Boot Carpet Damaged | Replace |
| Clutch Pedal Rubber Missing | Replace |
| Brake Pedal Rubber Torn / Cut | Replace |
| Steering Wheel Trim Defective | Repair |
| Number Plate Front Damaged | Replace |
| Side Mirror Left Paintwork • Scratched | Repair |
| Side Mirror Right Paintwork • Scratched | Repair |
| Front Bumper Damaged | Replace |
| Bonnet Paintwork • Scratched | Repair |
| Bonnet slam plate (Shock tower/ Inner tray) Cracked | Replace |
| B • Pillar Left Dented | Repair |
| B • Pillar Right Dented | Repair |
| C • Pillar Left Dented | Repair |
| Front Fender Left Dented | Repair |
| Front Fender Right Dented | Repair |
| Rear Fender Left Dented | Repair |
| Rear Fender Right Paintwork • Scratched | Repair |
| Front Fender Left / Inner Tray Damaged | Replace |
| Front Fender Right / Inner Tray Damaged | Replace |
| Door Front Left Damaged | Repair |
| Door Front Right Paintwork • Scratched | Repair |
| Door Rear Left Paintwork • Scratched | Repair |
| Door Rear Right Paintwork • Scratched | Repair |
| Boot Lid / Hatch door Paintwork • Scratched | Repair |
| Rear bumper Damaged | Repair |
| Inner Boot Floor Pan and Spare Wheel Well Dented | Repair |
| Sill Panel Left Paintwork • Scratched | Repair |
| Sill Panel Right Paintwork • Scratched | Repair |
| Rocker Panel Left Damaged | Replace |
| Rocker Panel Right Damaged | Repair |
| Sealing Window Front Door Right Damaged | Replace |
| Brake Pad 1. Axle left Defective | Replace |
| Brake Piping Defective | Repair |
| Shock Absorber Rear Left Leak | Replace |
| Stabilizer Mounting Front Left Defective | Replace |
| Stabilizer Mounting Front Right Defective | Replace |
| Rear Axle Defective | Repair |
| Tyre Front Left Damaged | Replace |
| Tyre Front Right Damaged | Replace |
| Tyre Rear Left Damaged | Replace |
| Tyre Rear Right Damaged | Replace |
| Spare Tyre Defective | Replace |
| Rim Front Left Scratched | Repair |
| Rim Front Right Scratched | Repair |
| Rim Rear Left Scratched | Repair |
| Rim Rear Right Scratched | Repair |
| Main Beam Left Defective | Repair |
| Chassis Damaged | Repair |
| Sub Frame Dented | Repair |
| Engine to silencer pipe Defective | Repair |
| Belly plates Damaged | Replace |
| Gearbox Oil Leak | Repair |
| Fuel Tank Damaged | Replace |

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

VIN: MJA4A51C2M1628976

Report No: 201628976

2 / 32

DATE

01/03/2024

| Damage | Repair Way |
|--|--|
| CV Joint(s) Boot(s) Front Left (inner/outer) Damaged | Replace |
| Radiator Cradle Damaged | Replace |
| Steering Malfunction | Repair |
| Engine Performance Idling / Hunting | Repair |
| Engine Smoke Excessive | Repair |
| Gear Selections Malfunction | Repair |
| Clutch Operation Insufficient | Repair |
| Engine | Engine bay dirty |
| Engine | Foreign substance on oil cap |
| Warning lights illuminated on dashboard | Repair |
| Tyres and Rims | Rear left and right tyre sizes different |
| Body and Exterior | Dents and scratches on some body panels |
| Body and Exterior | Some body panels misaligned |
| Body and Exterior | Stone chips and spray work on some body panels |
| Body and Exterior | Signs of impact damage to front of vehicle |
| Electrical components and Instruments | Speedometer not working |
| Road test | Engine performance insufficient |
| Interior | Vehicle interior dirty and some panels scratched |

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

VIN: MALA851CLGM388073

DATE
3/1/24
01/03/2024

Brakes

Brake Test Results

| | Left | Right | Axle Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | 2.02 | 2.51 | - | |
| Rear | 1.67 | 1.8 | - | |
| Emergency / Parking | 1.01 | 1.46 | - | |



CONDITION REPORT

Report No: 2016289146

DATE
VIN: MALA851C01039024
01/03/2024
4 / 32

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|------------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left | 175/65 R14 | 82H | Autogrip | Grip200 | V | 0222 | 2 mm |
| Front Right | 175/65 R14 | 82H | Autogrip | Grip200 | V | 0222 | 0 mm |
| Rear Left | 185/60 R14 | 82H | Dunlop | Sp-Sport | V | 1316 | 0 mm |
| Rear Right | 155/65 R14 | 75T | Goodyear | Efficient | V | 2521 | 0 mm |

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|----|-------------|-------|--|--------|
| 1 | ENG(ENGINE) | P0011 | INTAKE CAMSHAFT POSITION(CMP)A TIMING OVER-ADVANCE | |

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016289146


DATE
01/03/2024

VIN: MALA851CLGM388073


5 / 32



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

6 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

8 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



LF TYRE TREAD



LR TYRE TREAD

VIN: MALA851CLGM388073

9 / 32



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073
10 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024




ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Manual Transmission



Spare wheel Accessories

LGM388073
11 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

12 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Windscreen Wiper



Sealing Window Front Door Right



Seat Belt Front Right



Seat Front Right



Door Panel Front Right



Door Sealing Rubber Front Right

VIN: MALA851CLGM388073
13 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

14 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Sill Panel Right



B • Pillar Right

LGM388073
15 / 32



B • Pillar Right



Steering Wheel Trim



Clutch Pedal Rubber



Brake Pedal Rubber

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

16 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Sill Panel Right



Door Sealing Rubber Rear Right

VIN: MALA851CLGM388073

17 / 32



Door Panel Rear Right



Seat Belt Rear Left



Seat Rear



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

18 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146


DATE
01/03/2024



Door Front Right



Side Mirror Right



Front Fender Right



Rear Fender Right



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073
20 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Boot Lid / Hatch door



Windscreen Wiper



Tail Light Right



Tail Light Left

VIN: MALA851CLGM388073
21 / 32



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073
22 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Door Front Left



B • Pillar Left



Door Sealing Rubber Rear Left



Door Panel Rear Left



C • Pillar Left



Sill Panel Left

LA851CLGM388073
23 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

24 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Sill Panel Left



Seat Front Left



Door Sealing Rubber Front Left



Door Panel Front Left

LA851CLGM388073
25 / 32



Side Mirror Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073
26 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Front Bumper



Front Bumper



Front Bumper




Number Plate Front

VIN: MALA851CLGM388073
27 / 32



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

28 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146


DATE
01/03/2024



Engine Wiring



Engine Wiring



Engine



Air cleaner

VIN: MALA851CLGM388073

29 / 32



Water level



Battery box

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

30 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Battery box



Bonnet slam plate (Shock tower/ Inner tray)



Gear Selections



Heater control



Hooper



Hood Lining

VIN: MALA851CLGM388073
31 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

VIN: MALA851CLGM388073

32 / 32

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Steering



Park Light Rear Left



Bright Light Right



Dim Light Right



Park Light Front Right



Park Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Bright Light Left



Dim Light Left



Fog Light Front Right



Fog Light Front Left



Number Plate Light Left



Number Plate Light Right



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Boot Carpet



Parcel Tray



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Boot Lid / Hatch door



Spare Tyre



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Bonnet




Front Fender Right / Inner Tray



Tyre Front Right



Rim Front Right



Rim Rear Right



Rocker Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Tyre Rear Left



Tyre Rear Left



Rim Rear Left



Rocker Panel Left



Tyre Front Left



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Front Fender Left / Inner Tray



Engine Wiring



Engine Wiring



Tyre Front Right



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za





CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Engine



Gearbox



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)



Sub Frame



Main Beam Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Hoses



Chassis



Fuel Tank



Belly plates



Inner Boot Floor Pan and Spare Wheel Well



Shock Absorber Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024



Tyre Front Left



Dash Padding



Sill Panel Left



Door Lock Front Left



Switch Electrical Window Winder front right



Switch Electrical Window Winder front left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016289146

DATE
01/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za