



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/05/2025		M57 Pretoria Road - 1619
Inspection Date	07/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	KL18YJGP
Model	ATOS 1.1 50KW MOTION 5-DR AMT [2021-2024]	Register Number	
		Date Of First Licensing	
VIN	MALAF51CYNM170043	Last COR	
Engine Number		License Expiry Date	30/06/2024
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT METALLIC
Year Model	2022	Fuel	PETROL
Km Reading	87,364 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Indicator Light Front Left Missing	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Defective	Repair
Hood Lining Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Damaged	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Damage	Repair Way
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Right Dented	Repair
Windscreen Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Rim Front Right Scratched	Repair
Chassis Damaged	Repair
Sub Frame Dented	Repair
Engine	Foreign substance on oil cap
Engine	Engine bay dirty.
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Residual traces of repair on some body panels
Tyres and rims	Front and rear tyre sizes different
Tyres and rims	Front and rear hubcaps scratched
Body and Exterior	Stone chips and spray work on some body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.8	1.71	-	
Rear	1.19	1.28	-	
Emergency / Parking	1.07	0.79	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R14	82H	Habilead	Comfort	V	0113	0 mm
Front Right	175/65 R14	82T	Silverstone	Radial	V	5117	0 mm
Rear Left	175/70 R14	84T	Winrun	R330	V	2323	0 mm
Rear Right	175/65 R14	82H	Joyroad	Tour	V	1422	0 mm
Spare	155/80 R13	79T	MRF	ZVTV	V	4321	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AMT(AUTOMATED MANUAL TRANSMISSION)	P0820:16	TGS LEVER UNDERVOLTAGE	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR,

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: MALAF51CYNM170043

**CONDITION REPORT**

Report No: 2016867824

DATE
07/05/2025

ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Vehicle Information				Test Results			
Brand/Model	Car	Engine/Type	Car	Test Date	Test Time	Test Location	Test Result
Make/Model	Hyundai i10	Engine/Type	1.4L 16V	07/05/2025	10:00	DEKRA	PASS
Test Date	07/05/2025	Test Time	10:00	Test Location	DEKRA	Test Result	PASS
Vehicle ID	KL 18 VJ-6P	Engine/Type	1.4L 16V	Test Date	07/05/2025	Test Time	10:00
Test Result	PASS	Test Location	DEKRA	Test Date	07/05/2025	Test Time	10:00

Brake and shock absorber report

Vehicle Information				Test Results			
Brand/Model	Car	Engine/Type	Car	Test Date	Test Time	Test Location	Test Result
Make/Model	Hyundai i10	Engine/Type	1.4L 16V	07/05/2025	10:00	DEKRA	PASS
Test Date	07/05/2025	Test Time	10:00	Test Location	DEKRA	Test Result	PASS
Vehicle ID	KL 18 VJ-6P	Engine/Type	1.4L 16V	Test Date	07/05/2025	Test Time	10:00
Test Result	PASS	Test Location	DEKRA	Test Date	07/05/2025	Test Time	10:00

Diagnostic report page 1

Vehicle Information				Test Results			
Brand/Model	Car	Engine/Type	Car	Test Date	Test Time	Test Location	Test Result
Make/Model	Hyundai i10	Engine/Type	1.4L 16V	07/05/2025	10:00	DEKRA	PASS
Test Date	07/05/2025	Test Time	10:00	Test Location	DEKRA	Test Result	PASS
Vehicle ID	KL 18 VJ-6P	Engine/Type	1.4L 16V	Test Date	07/05/2025	Test Time	10:00
Test Result	PASS	Test Location	DEKRA	Test Date	07/05/2025	Test Time	10:00

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Seat Front Right



Seat Rear



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025


Side Mirror Right




Front Bumper



Front Bumper



Bonnet



Hood Lining



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Rear bumper



Boot Lid / Hatch door



Door Rear Left



Rear Fender Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Side Mirror Left



Seat Front Left



Indicator Light Front Left



Windscreen



Inner Boot Floor Pan and Spare Wheel Well



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Sill Panel Right



Tyre Rear Right



Tyre Front Right



Tyre Front Left



Sub Frame



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043



CONDITION REPORT

Report No: 2016867824

DATE
07/05/2025

Tyre Rear Right



Tyre Rear Left



Chassis



Rim Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAF51CYNM170043