



CONDITION REPORT



Report No:
2016906734
DATE
09/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/06/2025		M57 Pretoria Road - 1619
Inspection Date	09/06/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	JW70VHGP
Model	I10 1.1 MOTION 5-DR [2011-2018]	Register Number	
VIN	MALAN51BLGM659407	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2026
Color	SILVER	Power / Displacement	
Year Model	2016	Paint Finish	M - METALLIC
Km Reading	150,796 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLGM659407



Damage	Repair Way
Engine Oil Leak	Repair
Switch Electrical Window Winder rear left Malfunction	Repair
Switch Electrical Window Winder rear right Malfunction	Repair
Dim and Bright Indicator Light Malfunction	Repair
Dim Light Left Malfunction	Repair
Boot Carpet Missing	Replace
Front Bumper Paintwork • Discoloured	Repair
Bonnet Paintwork • Discoloured	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Front Left Smooth	Replace
Tyre Front Right Damaged	Replace
Spare Tyre Damaged	Replace
Engine to silencer pipe Welded	Repair
Antenna missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.1	2.0	-	
Rear	0.8	1.0	-	
Emergency / Parking	1	0.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/60R14	75H	Velocity	Rota -eco	V	5023	0 mm
Front Right	165/60R14	75H	Velocity	Rota -eco	V	5023	0 mm
Rear Left	165/60R14	75H	Velocity	Rota -eco	V	5023	3 mm
Rear Right	165/60R14	75H	Velocity	Rota -eco	V	5022	4 mm
Spare	165/60R14	75H	Dunlop	Sp sport	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1102	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Vehicle got some scratches, stone chips and dents. Discoloring on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

[illegible]

Shock and brake report

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT




90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick



Coolant bottle



Switch Electrical Window Winder rear left



Switch Electrical Window Winder rear right



Switch Electrical Window Winder rear right



Switch Electrical Window Winder rear left



Spare Tyre



Boot Carpet



Windscreen



Water level



Bonnet



Door Front Right



Door Rear Right



Rear Fender Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Boot Lid / Hatch door



Tyre Front Left



Tyre Front Right



Engine



Engine



Engine to silencer pipe



Dim and Bright Indicator Light



Dim Light Left

side-slip test				
Front axle	+19 m/km		Rear axle	-5 m/km
Shock absorber test (MSD3000)				
	left	right	Difference	Weight
Front axle	0.25	0.26	4 %	589 kg
Rear axle	> 0.30	0.29	3 %	388 kg
Total weight				977 kg
Brake test				
	Brake force		Difference	left
	left	right		
Front axle	2.16 kN	2.02 kN	7 %	--
Parking brake	1.02 kN	0.21 kN	79 %	--
Rear axle	0.89 kN	1.04 kN	15 %	69
Final evaluation static			64 %	
Deceleration service brake			13 %	
Deceleration parking brake				Total weight

Parking Brake Performance