

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	02/04/2024		M57 Pretoria Road - 1619
Inspection Date	02/04/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	KMZ187NW
Model	VENUE	Register Number	
VIN	MALFC81ALMM169834	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2023
Color	GREY	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	38,945 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items


VEHICLE INSPECTION

Damage

Repair Way

Front Bumper Paintwork • Scratched
Front Fender Left Dented
Rear Fender Left Paintwork • Scratched
Door Front Left Paintwork • Scratched
Door Rear Left Paintwork • Scratched
Rear bumper Paintwork • Scratched

Repair
Repair
Repair
Repair
Repair
Repair



Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.4	3.1	-	
Rear	1.7	1.6	-	
Emergency / Parking	1.4	1.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R16	95H	MRF	Wanderer	V	0421	5 mm
Front Right	215/60R16	95H	MRF	Wanderer	V	0421	4 mm
Rear Left	215/60R16	95H	MRF	Wanderer	V	0421	6 mm
Rear Right	215/60R16	95H	MRF	Wanderer	V	0421	5 mm
Spare	195/65R15	91H	Goodyear	Assurance	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: SIGNS OF SPRAY WORK DONE ON SOME BODY PANELS. ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE
ENGINE COVERED.

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016325199

VIN: MALFC81ALMM169834

DATE

02/04/2024



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



RR TYRE TREAD




LR TYRE TREAD

VIN: MALFC81ALMM169834

6 / 8



LF TYRE TREAD



RF TYRE TREAD




Sparewheel



Expansion bottle



Oil cap and dipstick



Rear end

VIN: MALFC81ALMM169834

7 / 8



CHASSIS



ENGINE 2




ENGINE 1




VIN PLATE OR STICKER




LICENSE DISC



SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



Front Bumper




Front Bumper



Front Fender Left




Door Front Left



Door Rear Left



Rear Fender Left



Rear Fender Left



Rear bumper



Rear bumper



CONDITION REPORT

Report No: 2016325199

DATE
02/04/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za