



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/06/2025		M57 Pretoria Road - 1619
Inspection Date	25/06/2025		Kempton Park - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	JZ89RRGP
Model	VENUE 1.0 88KW TGDI FLUID AT [2019-2023]	Register Number	
VIN	MALFC81AVMM169346	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2025
Color	GREY	Power / Displacement	
Year Model	2021	Paint Finish	M - METALLIC
Km Reading	66,949 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

**Vehicle Options & Accessories****Items****VEHICLE INSPECTION**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025

**Damage**

Hooter Defective	Repair
Headlight Left Scratched	Repair
Headlight Right Cracked	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair

**Repair Way****Brakes****Brake Test Results**

	Left	Right	Axe Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [kN]	Braking Force [kN]		
Front	3.5	3.7	-	
Rear	1.7	1.7	-	
Emergency / Parking	1	1.2	-	

**Tyres and Rims****Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R16	95H	MRF	Wanderer	V	0221	3 mm
Front Right	215/60R16	95H	MRF	Wanderer	V	0221	3 mm
Rear Left	215/60R16	95H	MRF	Wanderer	V	0221	4 mm
Rear Right	215/60R16	95H	MRF	Wanderer	V	0221	4 mm
Spare	195/65R15	91H	Goodyear	Assurance	V	0000	4 mm

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1346.00	DRIVER AIRBAG (DAB) RESISTANCE TOO HIGH (1ST STAGE)	

### Inspection Conditions

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025

Test results:

Parameter	Value	Unit	Description
Brake force	0.21	Nm	Front wheel
Brake force	0.22	Nm	Rear wheel
Brake force	0.21	Nm	Total front
Brake force	0.22	Nm	Total rear
Brake force	0.21	Nm	Average
Brake force	0.22	Nm	Weight
Brake force	0.21	Nm	Front weight
Brake force	0.22	Nm	Rear weight

Brake force:

Wheel	Front Left	Front Right	Rear Left	Rear Right
Front Left	0.21	0.21	0.21	0.21
Front Right	0.22	0.22	0.22	0.22
Rear Left	0.21	0.21	0.21	0.21
Rear Right	0.22	0.22	0.22	0.22

Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Expansion bottle

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025



Oil cap and dipstick



Water level



Bonnet



Boot Lid / Hatch door



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025



Front Bumper



Front Bumper



Headlight Left



Headlight Right



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksdorp, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346



## CONDITION REPORT



Report No:  
2016925114  
DATE  
25/06/2025



Rear Fender Right



Hooter

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MALFC81AVMM169346