



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	06/03/2024		M57 Pretoria Road - 1619
Inspection Date	06/03/2024		Kempton Park - GT


Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TATA	Registration Number	DH46FYGP
Model	INDICA	Register Number	
VIN	MAT600220DPR26418	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2019
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	292,652 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Hoses Oil Leak	Repair
Expansion Bottle Defective	Replace
Power Steering Pump / Electronic Unit Leak	Repair
Bonnet cable Missing	Replace
Bonnet safety caps Defective	Repair
Windscreen Wiper Damaged	Replace
Air Conditioner Insufficient	Replace
Tail Light Right Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Defective	Repair
Hood Lining Dirty	Repair
Door Panel Rear Left Defective	Repair
Door Panel Rear Right Defective	Repair
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Defective	Repair
Boot Panel Right Damaged	Replace
Clutch Pedal Rubber Missing	Replace
Brake Pedal Rubber Damaged	Replace
Steering Wheel Trim Defective	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
A • Pillar Left Dented	Repair
A • Pillar Right Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAT600220DPR26418

1 / 22



CONDITION REPORT

Report No: 2016295086

 DATE
06/03/2024

Damage	Repair Way
B • Pillar Left Dented	Repair
B • Pillar Right Dented	Repair
C • Pillar Left Dented	Repair
C • Pillar Right Dented	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Doorstopper Front Right Damaged	Replace
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Defective	Repair
Sill Panel Right Dented	Repair
Rocker Panel Left Damaged	Repair
Rocker Panel Right Damaged	Repair
Roof Damaged	Repair
Windscreen Cracked	Replace
Tie Rod End left Cracked	Replace
Tie Rod End right Cracked	Replace
Shock Absorber Rear Left Leak	Replace
Shock Absorber Rear Right Leak	Replace
Ball Joint(s) Front Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Spare Tyre Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Silencer Corrosion	Replace
Gearbox Mountings Defective	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Clutch Operation Noisy	Repair
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Body and Exterior	Some body panels misaligned
Body and Exterior	Signs of hail damage on some body panels
Engine	Engine bay dirty
Undercarriage	Vehicle undercarriage dirty.
Interior	Vehicle interior dirty and some panels scratched
Engine	Signs of vehicle overheating
Warning lights illuminated on dashboard	Repair
Axle and Suspension	Abnormal noise from front and rear suspension.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.63	3.08	-	
Rear	1.31	1.38	-	
Emergency / Parking	0.64	0.88	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

VIN: MAT6002201229508
Report No: 201629508
2 / 22
DATE
06/03/2024

Tyres and Rims
Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/65 R13	77T	Lanvigator	Comfort	V	0921	4 mm
Front Right	165/65 R13	77T	Lanvigator	Comfort	V	0221	4 mm
Rear Left	165/65 R13	77T	Lanvigator	Comfort	V	1823	5 mm
Rear Right	165/65 R13	77T	Lanvigator	Comfort	V	1823	4 mm
Spare	165/65 R13	77T	Goodyear	Ducaro	V	3013	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016295086

VIN: MAT600220DPR26418

DATE
06/03/2024

Vehicle Information				Inspection Details			
Vehicle No:	2204/014	Year:	2014	Inspection Date:	06/03/2024	Inspector:	DEKRA
Make:	MAHINDRA	Model:	MAHINDRA	Location:	PRETORIA	Client:	DEKRA
Engine No:	1747	Chassis No:	1747	Inspection Time:	10:00	Inspector:	DEKRA
Inspection							
Brake	OK	Shock	OK	Steering	OK	Wheels	OK
Engine	OK	Transmission	OK	Clutch	OK	Brake	OK
Light	OK	Signal	OK	Wiper	OK	Window	OK
Exhaust	OK	Seatbelt	OK	Door	OK	Lock	OK
Body	OK	Paint	OK	Interior	OK	Exterior	OK
Overall	PASS						

Brake and shock absorber report

Vehicle Information				Inspection Details			
Vehicle No:	2204/014	Year:	2014	Inspection Date:	06/03/2024	Inspector:	DEKRA
Make:	MAHINDRA	Model:	MAHINDRA	Location:	PRETORIA	Client:	DEKRA
Engine No:	1747	Chassis No:	1747	Inspection Time:	10:00	Inspector:	DEKRA
Inspection							
Brake	OK	Shock	OK	Steering	OK	Wheels	OK
Engine	OK	Transmission	OK	Clutch	OK	Brake	OK
Light	OK	Signal	OK	Wiper	OK	Window	OK
Exhaust	OK	Seatbelt	OK	Door	OK	Lock	OK
Body	OK	Paint	OK	Interior	OK	Exterior	OK
Overall	PASS						

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



CONDITION REPORT

Report No: 2016295086

DATE
VIN: MAT600226903/2014
06/03/2024
4 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418

5 / 22



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418
6 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


Report No: 2016295086

DATE
06/03/2024

LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418
8 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Manual Transmission



Steering Wheel Trim



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418
10 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024


Hood Lining



Air Conditioner



Side Mirror Right



Doorstopper Front Right



Seat Front Right



Clutch Pedal Rubber



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418

12 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Brake Pedal Rubber



Door Sealing Rubber Front Right



Sill Panel Right



Door Front Right



Side Mirror Right



Front Fender Right



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418

14 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Door Rear Right



Rear Fender Right



Door Panel Rear Right



Seat Rear



Rear bumper



Rear bumper



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418

16 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Boot Lid / Hatch door



Roof

VIN: MAT600220DPR26418

17 / 22



Rear Fender Left



Door Rear Left



Door Front Left



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418
18 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

B • Pillar Left



C • Pillar Left



Door Panel Rear Left



Seat Rear



Seat Front Left



Windscreen Wiper

VIN: MAT600220DPR26418
19 / 22



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418
20 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Windscreen



Front Fender Left



Front Bumper



Front Bumper



Bonnet



Headlight Right



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

VIN: MAT600220DPR26418
22 / 22

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Headlight Left



A • Pillar Right



B • Pillar Right



C • Pillar Right



Power Steering Pump / Electronic Unit



Engine



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Hoses



Rim Front Right



Rocker Panel Right



Rocker Panel Left



Rim Front Left



Rim Rear Left



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Shock Absorber Rear Left



Shock Absorber Rear Right



Rim Rear Right



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)



Gearbox



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Engine



Engine Wiring



Engine



Gearbox Mountings



Silencer



Rim Rear Left



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Ball Joint(s) Front Axle Left



Tie Rod End right



Tie Rod End left



Bonnet cable



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Bonnet cable



Water level



Expansion Bottle



Hoses



Engine Wiring



Engine Wiring



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

Bonnet safety caps



Boot Panel Right



Inner Boot Floor Pan and Spare Wheel Well



Spare Tyre



Tail Light Right



Parcel Tray



CONDITION REPORT

Report No: 2016295086

DATE
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

**CONDITION REPORT**

Report No: 2016295086

DATE
06/03/2024

Expansion Bottle

**CONDITION REPORT****Report No: 2016295086****DATE**
06/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za