



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 29/08/2025 | | M57 Pretoria Road - 1619 |
| Inspection Date | 29/08/2025 | | Kempton Park - GT |

Vehicle Data

| | | | |
|-----------------|--------------------------------|-------------------------|-------------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | SUZUKI | Registration Number | HFP348L |
| Model | SWIFT 1.2I GL 5-DR [2021-2025] | Register Number | |
| VIN | MBHCZC63S00941401 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | |
| Color | WHITE | Power / Displacement | |
| Year Model | 2022 | Paint Finish | M - METALLIC |
| Km Reading | 8,034 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

Vehicle Options & Accessories**Items****VEHICLE INSPECTION**

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025



| Damage | Repair Way |
|--|------------|
| Parcel Tray Missing | Replace |
| Side Mirror Left Paintwork • Scratched | Repair |
| Front Bumper Paintwork • Scratched | Repair |
| Rear Fender Left Paintwork • Scratched | Repair |
| Door Front Left Paintwork • Scratched | Repair |
| Door Front Right Dented | Repair |
| Door Rear Left Paintwork • Scratched | Repair |
| Door Rear Right Paintwork • Scratched | Repair |
| Rear bumper Paintwork • Scratched | Repair |
| Sill Panel Left Dented | Repair |
| Windscreen washers not working | Repair |
| License disc missing | Replace |

Brakes

Brake Test Results

| | Left | Right | Axe Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|-----------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | 1.6 | 1.5 | - | |
| Rear | 1.1 | 1.0 | - | |
| Emergency / Parking | 0.7 | 0.8 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|------------|------------------|-------------|------------|-------|-----------------|------------------|
| Front Left | 185/70R14 | 88H | Royal black | Royal mile | V | 2723 | 3 mm |
| Front Right | 185/70R14 | 88H | Royal black | Royal mile | V | 2723 | 3 mm |
| Rear Left | 185/70R14 | 88H | Royal black | Royal mile | V | 2723 | 3 mm |
| Rear Right | 185/70R14 | 88H | Royal black | Royal mile | V | 2723 | 3 mm |
| Spare | T135/70R15 | 99M | Jk tyre | Temporary | V | 0000 | 4 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|----|---------|-------|--|--------|
| 1 | HISTORY | C1037 | STEERING ANGLE SENSOR POWER SUPPLY VOLTAGE | |

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT

Report No:
2016996304
DATE
29/08/2025



REAR LEFT CORNER



FRONT RIGHT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025



RF TYRE TREAD



RR TYRE TREAD




Spare wheel



Coolant bottle



Oil cap and dipstick



Shock and brake report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT

Report No:
2016996304
DATE
29/08/2025



ENGINE 1



CHASSIS




ENGINE 2



VIN PLATE OR STICKER



LICENSE DISC MISSING



DIAGNOSTIC REPORT PAGE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT

Report No:
2016996304
DATE
29/08/2025



DIAGNOSTIC REPORT PAGE 2



Parcel Tray



Door Rear Right



Door Front Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025



Side Mirror Left



Rear Fender Left



Door Rear Left



Sill Panel Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401



CONDITION REPORT



Report No:
2016996304
DATE
29/08/2025



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZC63S00941401