



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	13/09/2024		M57 Pretoria Road - 1619
Inspection Date	13/09/2024		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	JS39JFGP
Model	ETIOS	Register Number	
VIN	MBJK29BT600053941	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	29/09/2023
Color	BLUE	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	300,856 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Door Handle Front Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Shock Absorber Rear Left Worn	Replace
Stabilizer Front Missing	Replace
Mounting Rubber(s) Rear Axle Left Worn	Replace
Mounting Rubber(s) Rear Axle Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBJK29BT600053941



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

Damage	Repair Way
Tyre Rear Right Worn	Replace
Engine to silencer pipe Damaged	Replace
Gearbox Oil Leak	Repair
Radiator Cradle Damaged	Repair
Engine	Sump damage
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Vehicle body and poor condition.
Body and exterior	Repair work done to vehicle below standard.
Body and exterior	Poor alignment to somebody panels.
Vehicle	vehicle electronics malfunctioning.
Vehicle	vehicle struggles to idle.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.43	2.76	-	
Rear	1.07	1.27	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Firestone	Radial	V	4721	0 mm
Front Right	185/60R14	82H	Firestone	Radial	V	4721	0 mm
Rear Left	185/60R14	82H	Goodyear	Efficient	V	1819	2 mm
Rear Right	185/65R14	86H	llink	Radial	V	3220	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P1604	STARTABILITY FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


VIN: MB1K29B5600053041

Report No: 2016531573


2 / 13

DATE

13/09/2024



Brake and shock test



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



CONDITION REPORT

Report No: 2016531573

VIN: MBJK29BT600053941

DATE

13/09/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
VIN: MJBK29BT600053941
13/09/2024
4 / 13



ODOMETER



manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

VIN: MBJK29BT600053941

5 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

VIN: MJBK29BT600053941

6 / 13



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

VIN: MBJK29BT600053941
7 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024



ENGINE 1



undercarriage front.

600053941
8 / 13



undercarriage rear.



oil cap and dipstick.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

VIN: MBJK29BT600053941
9 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

Front Bumper



Bonnet



Front Fender Left



Rear Fender Right



Rear Fender Left



Door Front Left



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

VIN: MBJK29BT600053941
11 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024



Door Rear Left



Rear bumper

VIN: MJBK29BT600053941
12 / 13



Rear bumper



Boot Lid / Hatch door



Front Fender Right



Door Front Right



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

VIN: MBJK29BT600053941
13 / 13

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

Door Rear Right



Roof



Windscreen



Seat Front Right



Seat Rear



Seat Front Left



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

Door Handle Front Right



Tail Light Left



Tail Light Right



Headlight Right



Headlight Left



Shock Absorber Rear Left



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

Radiator Cradle



Engine



Gearbox



Engine to silencer pipe



Tyre Front Left



Tyre Front Right



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

Tyre Rear Right



Mounting Rubber(s) Rear Axle Left



Mounting Rubber(s) Rear Axle Right



Stabilizer Front



CONDITION REPORT

Report No: 2016531573

DATE
13/09/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za