



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	21/02/2024		M57 Pretoria Road - 1619
Inspection Date	21/02/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	JS73PCGP
Model	ALMERA	Register Number	
VIN	MDHBBAN17Z0731331	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2023
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	83,756 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Air Conditioner Insufficient	Repair
Tail Light Right Damaged	Repair
Boot Panel Left Damaged	Repair
Boot Panel Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Welded	Repair
Sill Panel Left Damaged	Repair
Roof Damaged	Repair
Main Beam Left Damaged	Repair
Main Beam Right Damaged	Repair
Radiator Cradle Damaged	Repair
Brakes Noisy	Repair
Engine	Battery lose.
Body and exterior.	Minor dents and scratches and stone chips.
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Signs of impact damage to rear of vehicle.
Body and exterior	Signs of impact damage to front of vehicle.
Body and exterior	Poor alignment to some body panels.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0731331

1 / 12



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

Damage	Repair Way
Body and exterior	Signs of hail damage to some body panels.
Body and exterior	Vehicle body in poor condition.
Body and exterior	Repair work done to vehicle below-standard.
Body and exterior	Front bumper stiffener damaged
Body and exterior and undercarriage	Vehicle is a cut and join.
Vehicle electronics	Interior fans not working.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.58	2.69	-	
Rear	2.08	2.16	-	
Emergency / Parking	1.34	1.46	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Lanvigator	Radial	V	2023	3 mm
Front Right	185/65R15	88H	Lanvigator	Radial	V	2023	3 mm
Rear Left	185/65R15	88H	Lanvigator	Radial	V	2023	3 mm
Rear Right	185/65R15	88H	Lanvigator	Radial	V	2023	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT


VIN: MDHBAW176276051
Report No: 2046276051
2 / 12
DATE
21/02/2024



Brake test



diagnostics



diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051
VIN: MDHBBAN17Z0731331
DATE
3/12
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
VIN: MDHBBAN 270272824
4/12



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

VIN: MDHBBAN17Z0731331

5 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

VIN: MDHBBAN17Z0731331

6 / 12



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

VIN: MDHBBAN17Z0731331
7 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

ENGINE 1



Chassis 1

7Z0731331
8 / 12

Chassis 2



Automatic.



Oil cap and dipstick



Water level



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

VIN: MDHBBAN17Z0731331
9 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

Bonnet




Bonnet



Front Bumper



Front Bumper



Front Fender Left



Rear Fender Left



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

VIN: MDHBBAN17Z0731331

11 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

Door Front Left



Door Rear Left

VIN: MDH8BAN17Z0731331
12 / 12

Rear bumper



Rear bumper



Boot Lid / Hatch door



Inner Boot Floor Pan and Spare Wheel Well



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

Inner Boot Floor Pan and Spare Wheel Well



Boot Panel Left



Boot Panel Right



Rear Fender Right



Front Fender Right



Door Front Right



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

Door Rear Right



Roof




Tail Light Right



Sill Panel Left



Front Bumper



Radiator Cradle



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016276051

DATE
21/02/2024

Main Beam Right



Main Beam Left



Main Beam Left



Inner Boot Floor Pan and Spare Wheel Well



Air Conditioner

**CONDITION REPORT****Report No: 2016276051****DATE**
21/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za