

CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025

MFC Auction House M57 Pretoria Rd, Glenmarais, KEMPTON PARK Gauteng











MFC

LB50YNGP

28/02/2026



Assignment

Client MFC Auction House Requested Date 01/07/2025 01/07/2025 Inspection Date

Inspection Location MFC

M57 Pretoria Road - 1619 Kempton Park - GT

Vehicle Data

Engine Number

Year Model

Vehicle Type PASSENGER VEHICLE Manufacturer NISSAN Model

MAGNITE TURBO 1.0T ACENTA W/O LED 5-

DR [2022-2024]

WHITE

2023

MDHFBADD0Z0011310

Register Number Date Of First Licensing

Registration Number

Last COR

License Expiry Date

Registered Owner

Power / Displacement

Paint Finish TWO COAT UNI Fuel PETROL Transmission MANUAL

Km Reading 15,260 KM НАТСНВАСК Cab / Body Type

Vehicle Options & Accessories

Items

Doors

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025



| Damage | Repair Way | |
|-------------------------------|------------|--|
| Engine Oil Sweat | Repair | |
| Headlight Right Damaged | Replace | |
| Front Bumper Damaged | Repair | |
| Bonnet Damaged | Repair | |
| Front Fender Left Damaged | Repair | |
| Front Fender Right Damaged | Repair | |
| Rear Fender Left Damaged | Repair | |
| Rear Fender Right Damaged | Repair | |
| Door Front Left Damaged | Repair | |
| Door Front Right Damaged | Repair | |
| Door Rear Left Damaged | Repair | |
| Door Rear Right Damaged | Repair | |
| Boot Lid / Hatch door Damaged | Repair | |
| Rear bumper Damaged | Repair | |
| Gearbox Oil Leak | Repair | |
| Radiator Cross Member Damaged | Repair | |

Brakes Brake Test Results

| | Left | Right | | |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s ²] |
| Front | 2.82 | 2.77 | - | |
| Rear | 1.45 | 1.68 | - | |
| Emergency / Parking | 1.03 | 1.28 | - | |

Tyres and Rims Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|--------|-------|------------------------|------------------|
| Front Left | 195/60R16 | 89V | Ceat | Radial | V | 4222 | 2 mm |
| Front Right | 195/60R16 | 89V | Ceat | Radial | V | 3922 | 3 mm |
| Rear Left | 195/60R16 | 89V | Ceat | Radial | V | 4222 | 3 mm |
| Rear Right | 195/60R16 | 89V | Ceat | Radial | V | 3922 | 3 mm |

^{*} Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|----|---------|----------|-----------------------|--------|
| 1 | CLUSTER | B1411:13 | OIL PRESSURE INPUT CO | |

Inspection Conditions

No Test Drive Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose.

Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Repair work done to vehicle below standard. Vehicle body in poor condition. Signs of impact damage to front of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT




Report No: 2016930942 DATE 01/07/2025



Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025













DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025













DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025



LICENSE DISC





ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025





Headlight Right



Front Bumper





Bonnet



Front Fender Left

DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025







Door Front Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door


DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za





CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025











Door Front Right







DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za



CONDITION REPORT



Report No: 2016930942 DATE 01/07/2025



DEKRA Automotive (PTY) Ltd. 97 Willem Cruywagen Ave Klerksoord, Pretoria, 0200 Phone: 012 542 4867 www.dekraauto.co.za