

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 14/02/2025        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 14/02/2025        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                   |                         |                   |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        | MFC AUCTION HOUSE |
| Manufacturer    | RENAULT           | Registration Number     | JK22WGGP          |
| Model           | KWID              | Register Number         |                   |
| VIN             | MEEBBA00500702064 | Date Of First Licensing |                   |
| Engine Number   |                   | Last COR                |                   |
| Doors           | 5                 | License Expiry Date     | 31/05/2025        |
| Color           | GREEN             | Power / Displacement    |                   |
| Year Model      |                   | Paint Finish            | M - METALLIC      |
| Km Reading      | 135,903 KM        | Fuel                    | PETROL            |
| Cab / Body Type | HATCHBACK         | Transmission            | MANUAL            |

## Vehicle Options & Accessories

### Items

## VEHICLE INSPECTION

| Damage                                     | Repair Way |
|--------------------------------------------|------------|
| Dim and Bright Indicator Light Malfunction | Repair     |
| Parcel Tray Missing                        | Replace    |
| Front Bumper Paintwork • Scratched         | Repair     |
| Bonnet Dented                              | Repair     |
| Rear Fender Left Dented                    | Repair     |
| Door Front Right Dented                    | Repair     |
| Door Rear Left Dented                      | Repair     |
| Door Rear Right Paintwork • Scratched      | Repair     |
| Boot Lid / Hatch door Dented               | Repair     |
| Rear bumper Dented                         | Repair     |
| Windscreen Chipped                         | Repair     |
| Boot not closing properly                  | Repair     |
| Sludge on oil cap                          | Repair     |
| L/F hub cap missing                        | Replace    |

## Brakes

### Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 1.9                | 2.1                | -                |                                  |
| Rear                | 1.2                | 1.2                | -                |                                  |
| Emergency / Parking | 0.7                | 0.7                | -                |                                  |

## Tyres and Rims

### Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model   | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|---------|-------|-----------------|------------------|
| Front Left  | 175/65R14 | 82T              | Road stone  | Eurovis | V     | 5121            | 3 mm             |
| Front Right | 175/65R14 | 82T              | Road stone  | Eurovis | V     | 5121            | 3 mm             |
| Rear Left   | 165/70R14 | 81T              | Apollo      | Amazer  | V     | 4619            | 4 mm             |
| Rear Right  | 175/65R14 | 82T              | Road stone  | Eurovis | V     | 5121            | 4 mm             |
| Spare       | 175/65R14 | 82T              | Road stone  | Eurovis | V     | 0000            | 5 mm             |

\* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code      | Description                          | Status |
|----|--------|-----------|--------------------------------------|--------|
| 1  | MEMORY | DTC033564 | ENGINE SPEED SENSOR SIGNAL PLAUSIBLY |        |

## Inspection Conditions

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS MINOR DENTS, SCRATCHES & STONE CHIPS ON VARIOUS BODY PANELS.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER

VIN: MEEBBA00500702064

2 / 9



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

VIN: MEEBBA00500702064

3 / 9



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual

VIN: MEEBBA00500702064

4 / 9



LF TYRE TREAD



LR TYRE TREAD

VIN: MEEBBA00500702064

5 / 9



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



Coolant bottle



Oil cap and dipstick



ENGINE 2

VIN: MEEBBA00500702064





CHASSIS



ENGINE 1



VIN PLATE OR STICKER



LICENSE DISC




SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1

VIN: MEEBBA00500702064

8 / 9



DIAGNOSTIC REPORT PAGE 2



Parcel Tray

VIN: MEEBBA00500702064

9 / 9



Water level



Bonnet



Door Rear Right



Door Front Right





Front Bumper



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door





Windscreen



Dim and Bright Indicator Light



Dim and Bright Indicator Light



## CONDITION REPORT

Report No: 2016762833

DATE  
14/02/2025

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)