



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	20/03/2024		M57 Pretoria Road - 1619
Inspection Date	20/03/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	KP64VBGP
Model	AVANZA	Register Number	
VIN	MHKM5FB2N0K002339	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	20/03/2024
Color	GOLDEN	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	134,969 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Battery clamps Defective	Replace
Indicator Light Front Left Damaged	Replace
Indicator Light Front Right Damaged	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Seat Front Right Torn / Cut	Repair
Seat Rear Torn / Cut	Repair
Sun Visor Left Missing	Replace
Door Panel Front Right Damaged	Repair
Carpet Rear Torn / Cut	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Welded	Repair
A • Pillar Right Dented	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Left Dented	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Right / Inner Tray Welded	Replace
Door Front Right Damaged	Replace
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Replace
Rear bumper Damaged	Repair
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MHKM5FB2N0K002339

1 / 19



## CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

Damage	Repair Way
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Shock Absorber Rear Left Leak	Replace
Shock Absorber Rear Right Leak	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Rim Front Right Damaged	Repair
Radiator Cradle Damaged	Replace
Body exterior.	Residual traces of poor repair work done on all b
Body exterior.	Minor dents scratches and stone chips on some bod.
Body exterior.	Signs of spray work done on all body panels.
Bottom of engine is fully covered	Body exterior
Comments	Vehicle is possible a code 3
Warning light illuminated	Repair
Driver window not closing properly	Repair

### Brakes

#### Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	1.2	2.6	-	
Rear	2.1	0.1	-	
Emergency / Parking	1.5	0.8	-	

### Tyres and Rims

#### Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	88H	Symmetry	SY101	V	4621	5 mm
Front Right	185/70R14	88H	Cachland	CH268	V	1722	1 mm
Rear Left	195R14	106/104R	Hilo	Brawin	V	2021	1 mm
Rear Right	195R14	106/104R	Hilo	Brawin	V	2021	1 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive  
 Vehicle doesn't start  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. VEHICLE IS CUT & JOIN.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za



CONDITION REPORT

VIN: MLKMF8201692387

Report No: 2016912387

2 / 19

DATE

20/03/2024

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za




CONDITION REPORT


Report No: 2016312367

VIN: MHKM5FB2N0K002339


DATE 3/20/2024



Shock and brake report



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

VIN: MHKM5FB2106002824  
DATE: 20/03/2024  
4 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

VIN: MHKM5FB2N0K002339

5 / 19



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016312367**

**DATE**  
**20/03/2024**

VIN: MHKM5FB2N0K002339

6 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024




90 DEGREE LEFT



LF TYRE TREAD




RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



No sparewheel

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016312367**

**DATE**  
**20/03/2024**

VIN: MHKM5FB2N0K002339

8 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



No license disc



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



Rear end

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

VIN: MHKMS5FB2N0K002339

10 / 19


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Missing panels



Warning light illuminated



Oil cap and dipstick



Coolant reservoir



L/R quarter window broken

Vehicle Information

Brand	Model	Year	Color	Registration
Hyundai	Elantra	2018	White	12345678
Engine	Capacity	Power	Transmission	Drive
1.8L	100 kW	120 hp	Manual	FWD
Weight	Wheelbase	Ground Clearance	Seating Capacity	Doors
1200 kg	2500 mm	150 mm	5	4

Brake Test Results

Wheel	Brake Force (kN)	Brake Force (kg)	Efficiency (%)
Front Left	1.21	123	85
Front Right	1.18	120	82
Rear Left	0.95	97	78
Rear Right	0.92	94	75

Additional Data:

- Rolling Resistance: 0.012
- Rolling Resistance (with load): 0.015
- Rolling Resistance (with load, 20% slip): 0.018
- Rolling Resistance (with load, 40% slip): 0.022
- Rolling Resistance (with load, 60% slip): 0.028
- Rolling Resistance (with load, 80% slip): 0.035
- Rolling Resistance (with load, 100% slip): 0.045

Parking Brake Performance

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

VIN: MHKM5FB2N0K002339

12 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MHKM5FB2N0K002339  
13 / 19

Vehicle size		Wheelbase		Wheel track	
Front overhang	1410 mm	Front	1410 mm	Front	1410 mm
Rear overhang	1020 mm	Rear	1020 mm	Rear	1020 mm
Wheelbase	2430 mm	Front	1410 mm	Rear	1020 mm
Track front	1510 mm	Front	1410 mm	Rear	1020 mm
Track rear	1510 mm	Front	1410 mm	Rear	1020 mm
Track rear (inner)	1410 mm	Front	1410 mm	Rear	1020 mm
Track rear (outer)	1610 mm	Front	1410 mm	Rear	1020 mm
Track rear (inner)	1410 mm	Front	1410 mm	Rear	1020 mm
Track rear (outer)	1610 mm	Front	1410 mm	Rear	1020 mm
Track rear (inner)	1410 mm	Front	1410 mm	Rear	1020 mm
Track rear (outer)	1610 mm	Front	1410 mm	Rear	1020 mm

Service Brake Performance Rear Axle

Vehicle size		Wheelbase		Wheel track	
Front overhang	1410 mm	Front	1410 mm	Front	1410 mm
Rear overhang	1020 mm	Rear	1020 mm	Rear	1020 mm
Wheelbase	2430 mm	Front	1410 mm	Rear	1020 mm
Track front	1510 mm	Front	1410 mm	Rear	1020 mm
Track rear	1510 mm	Front	1410 mm	Rear	1020 mm
Track rear (inner)	1410 mm	Front	1410 mm	Rear	1020 mm
Track rear (outer)	1610 mm	Front	1410 mm	Rear	1020 mm
Track rear (inner)	1410 mm	Front	1410 mm	Rear	1020 mm
Track rear (outer)	1610 mm	Front	1410 mm	Rear	1020 mm
Track rear (inner)	1410 mm	Front	1410 mm	Rear	1020 mm
Track rear (outer)	1610 mm	Front	1410 mm	Rear	1020 mm

Service Brake Performance Front Axle



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

VIN: MHKM5FB2N0K002339

14 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)

VIN: MHKM5FB2N0K002339

15 / 19



Headlight Left



Bonnet



Bonnet



Battery clamps

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

VIN: MHKM5FB2N0K002339

16 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray) VIN: MHK1M5P2ZN0K002339

17 / 19



Front Bumper



Tail Light Left



Tail Light Right



A • Pillar Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

VIN: MHKM5FB2N0K002339

18 / 19

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Side Mirror Right



Front Fender Right



Door Front Right



Front Fender Right / Inner Tray



Front Fender Right / Inner Tray



Front Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Control Arm Bush(es) Front Axle Right



Indicator Light Front Right



Front Bumper



Front Bumper



Front Fender Left



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Control Arm Bush(es) Front Axle Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



Rear Fender Right



Radiator Cradle




Radiator Cradle



Shock Absorber Rear Left



Shock Absorber Rear Right



Rim Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

Report No: 2016312367

DATE  
20/03/2024


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024




Seat Front Right




Door Rear Right



C • Pillar Right



Rear bumper



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024




DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016312367

DATE  
20/03/2024



DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016312367**

**DATE**  
**20/03/2024**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za