



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
GautengDEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	03/05/2024		M57 Pretoria Road - 1619
Inspection Date	03/05/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	FKF675L
Model	AVANZA	Register Number	
VIN	MHKM5FB2N0K002814	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	29/02/2024
Color	GOLDEN	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	224,264 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Central Air Vent Damaged	Replace
Engine Management Lights Set	Repair
Tail Light Right Damaged	Replace
Seat Front Right Damaged	Repair
Hood Lining Damaged	Repair
Carpet Front Damaged	Repair
Carpet Rear Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Shock Absorber Rear Right Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Sweat	Repair
Brakes Insufficient	Repair
Cluster	Cluster dirty
Body and exterior	Signs of repair work done to somebody panels.
Body and exterior	Repair work done to vehicle below standard.
Body and exterior	Poor alignment to somebody panels.
interior	Vehicle interior dirty.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MHKM5FB2N0K002814

1 / 12



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

Damage

Brake's
Undercarriage

Repair Way

Vehicle brakes fading away
Bottom of engine and gearbox fully cover.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	0.63	2.8	-	
Rear	2.76	0.13	-	
Emergency / Parking	0.65	0.37	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	91T	Hilo	Radial	V	4018	2 mm
Front Right	185/70R14	88H	Symmetry	Radial	V	4821	0 mm
Rear Left	185/70R14	88H	Rapid	Radial	V	1323	2 mm
Rear Right	185/70R14	88T	Tracmax	Radial	V	4321	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS (5 DTCS)	C0205	FL WHEEL OPEN WIRE/SHORTED	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE


Technician

Werner Laubscher


This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



Brake and shock test



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470
VIN: MHKM5FB2N0K002814
DATE
03/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
VIN: MHKM5FB2N9K6902814
05/05/2024
4/12



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

VIN: MHKM5FB2N0K002814

5 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470


DATE
03/05/2024

VIN: MHKM5FB2N0K002814


6 / 12



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

VIN: MHKM5FB2N0K002814
7 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

VIN PLATE OR STICKER




ENGINE 1

VIN: MHKM5FB2N0K002814

8 / 12



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

VIN: MHKM5FB2N0K002814
9 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left



Door Rear Left



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

VIN: MHKM5FB2N0K002814

11 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

Rear Fender Left




Rear bumper

VIN: MHKM5FB2N0K002814
12 / 12


Rear bumper



Boot Lid / Hatch door



Door Rear Right



Door Front Right



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

Front Fender Right



Rear Fender Right



Carpet Rear



Carpet Rear



Carpet Front



Carpet Front



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

Seat Front Right



Tail Light Right



Shock Absorber Rear Right



Gearbox



Tyre Front Right



Tyre Rear Right



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016364470

DATE
03/05/2024

Engine Management Lights



Central Air Vent



Hood Lining

**CONDITION REPORT****Report No: 2016364470****DATE**
03/05/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za