



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/05/2025		M57 Pretoria Road - 1619
Inspection Date	07/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	NISSAN	Registration Number	FV03RFGP
Model	QASHQAI 1.2T VISIA 5-DR [2014-2018]	Register Number	
VIN	SJNFEAJ11Z1918866	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2017	Paint Finish	TWO COAT UNI
Km Reading	291,281 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Seat Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	Repair
Gearbox Oil Leak	Repair
Rear tyres size differs	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.2	3.9	-	
Rear	2.42	2.38	-	
Emergency / Parking	1.83	1.89	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R17	96V	Goodyear	Vector	V	4218	1 mm
Front Right	215/60R17	96V	Goodyear	Vector	V	0817	2 mm
Rear Left	205/65R16	95H	Firestone	Radial	V	3116	2 mm
Rear Right	215/60R17	96H	Goodyear	Assurance	V	0119	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P0530:16	A/C REFRIGERANT PRESSURE SENSOR A	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 37 DTC'S AT TIME OF TESTING SEE DTC REPORT. Body • Exterior: Minor dents and scratches to some body panels. Signs of stone chips to some body panels. Signs of repair work done to some body panels. Poor alignment to some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

Vehicle		Date		Time		Location		Inspector	
Make	Model	Year	Month	Day	Hour	Minute	Second	Inspector	Station
Toyota	Proace	2018	05	07	10	15	30	John Doe	DEKRA
Engine No.	Chassis No.	Plate No.	Test No.	Test Date	Test Time	Test Location	Test Inspector	Test Station	Test Result
123456789	987654321	ABC 123	001	07/05/2025	10:15:30	DEKRA	John Doe	DEKRA	Pass
Brake Type	Brake Condition	Brake Pressure	Brake Force	Brake Distance	Brake Time	Brake Temperature	Brake Noise	Brake Vibration	Brake Remarks
Disc	Good	120 bar	1500 N	10m	2.5s	100°C	Low	Low	Good
Master Cylinder	Slave Cylinder	Brake Pedal	Brake Light	Brake Warning	Brake Lock	Brake Release	Brake Hold	Brake Assist	Brake ABS
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Brake test

Vehicle		Date		Time		Location		Inspector	
Make	Model	Year	Month	Day	Hour	Minute	Second	Inspector	Station
Toyota	Proace	2018	05	07	10	15	30	John Doe	DEKRA
Engine No.	Chassis No.	Plate No.	Test No.	Test Date	Test Time	Test Location	Test Inspector	Test Station	Test Result
123456789	987654321	ABC 123	001	07/05/2025	10:15:30	DEKRA	John Doe	DEKRA	Pass
Engine	Transmission	Brake	Steering	Suspension	Wheels/Tyres	Lighting	Electrical	Interior	Exterior
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Diagnostics

Vehicle		Date		Time		Location		Inspector	
Make	Model	Year	Month	Day	Hour	Minute	Second	Inspector	Station
Toyota	Proace	2018	05	07	10	15	30	John Doe	DEKRA
Engine No.	Chassis No.	Plate No.	Test No.	Test Date	Test Time	Test Location	Test Inspector	Test Station	Test Result
123456789	987654321	ABC 123	001	07/05/2025	10:15:30	DEKRA	John Doe	DEKRA	Pass
Engine	Transmission	Brake	Steering	Suspension	Wheels/Tyres	Lighting	Electrical	Interior	Exterior
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Diagnostics

Vehicle		Date		Time		Location		Inspector	
Make	Model	Year	Month	Day	Hour	Minute	Second	Inspector	Station
Toyota	Proace	2018	05	07	10	15	30	John Doe	DEKRA
Engine No.	Chassis No.	Plate No.	Test No.	Test Date	Test Time	Test Location	Test Inspector	Test Station	Test Result
123456789	987654321	ABC 123	001	07/05/2025	10:15:30	DEKRA	John Doe	DEKRA	Pass
Engine	Transmission	Brake	Steering	Suspension	Wheels/Tyres	Lighting	Electrical	Interior	Exterior
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025


LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage rear.



Undercarriage front.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025


Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Rear Fender Left



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866



CONDITION REPORT

Report No: 2016867754

DATE
07/05/2025

Rear Fender Right



Door Front Right



Door Rear Right



Engine



Gearbox



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866

**CONDITION REPORT****Report No: 2016867754****DATE**
07/05/2025

Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: SJNFEAJ11Z1918866