



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/01/2024		M57 Pretoria Road - 1619
Inspection Date	09/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	FRJ108L
Model	CLIO	Register Number	
VIN	VF15RSV0A61441020	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2023
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	82,057 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Wiring Defective	Repair
Hoses Oil Sweat	Repair
Center Console / Cubbyhole + Lid Defective	Repair
Switch Electrical Window Winder front left Missing	Replace
Electrical Window Winder rear right Malfunction	Replace
Windscreen Wiper Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Dented	Repair
Door Rear Left Damaged	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Rocker Panel Left Damaged	Repair
Rocker Panel Right Dented	Repair
Roof Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A61441020

1 / 17



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Damage	Repair Way
Windscreen Chipped	Repair
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Tyre Rear Right Defective	Replace
Spare Tyre Damaged	Replace
Rim Front Right Dented	Repair
Chassis Dented	Repair
Sub Frame Damaged	Replace
Belly plates Damaged	Replace
Radiator Cradle Dented	Repair
Warning lights illuminated on dashboard	Repair

Brakes**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	2.42	2.52	-	-
Rear	2.29	0.78	-	-
Emergency / Parking	1.59	0.52	-	-

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55 R16	91V	Autogrip	P308	V	4520	2 mm
Front Right	195/55 R16	87V	Linglong	Green-Max	V	0621	2 mm
Rear Left	195/55 R16	91V	Autogrip	P308	V	4520	3 mm
Rear Right	185/65 R15	88T	Barum	Brillantis	V	2918	7 mm
Spare	195/55 R16	87H	Continental	ContiEco	V	2618	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC056016	COMPUTER SUPPLY VOLTAGE PERMANENT LOW LEVEL	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.
 Engine Compartment: Engine bay dirty. Brake fluid level ok. Corrosion on battery box.
 Electrical Components and Instruments: Radio need authentication key to operate.
 Interior: Vehicle interior dirty and some interior panels scratched.
 Body • Exterior: Dents and scratches on some body panels. Spray work on some body panels. Some body panels misaligned. Stone chips on some body panels.
 Signs of impact damage to front of vehicle.
 Brakes: Rear right wheel binding.
 Axle and Suspension: Abnormal noise coming from front and rear suspension.
 Tyres and Rims: Alloy rims scratched. Original spare wheel fitted to rear right side of vehicle. Rear left and right tyre sizes different.
 Undercarriage: Vehicle undercarriage dirty. Bottom of engine and gearbox fully covered. Exhaust rusted.
 Road Test: Vehicle unsafe to drive due to rear right wheel binding.

Concluding Remarks

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksdorp, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za



CONDITION REPORT

VIN/VF150SV20162210837

Report No 20162210837

2 / 17

DATE

09/01/2024

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016221837

VIN: VF15RSV0A61441020

DATE

09/01/2024

Brake and shock absorber report

Diagnostic report page 1

Diagnostic report page 2

Diagnostic report page 3

Diagnostic report page 4





CONDITION REPORT

Report No: 2016221837

DATE

VIN: VF15RSV0090442024

4 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

5 / 17



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

6 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

7 / 17



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

8 / 17

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Spare wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

10 / 17



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Oil cap and dipstick



Manual Transmission



Seat Front Right



Seat Rear



Electrical Window Winder rear right



Sill Panel Right



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

12 / 17



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Sill Panel Right



Sill Panel Left



Seat Rear



Sill Panel Left



Seat Front Left



Switch Electrical Window Winder front left



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

14 / 17



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Windscreen Wiper



Side Mirror Left



Bonnet



Front Bumper



Front Bumper



Windscreen



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

VIN: VF15RSV0A61441020

16 / 17



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Rear bumper




Rear bumper

VIN: VF15RSV0A61441020
17 / 17

Center Console / Cubbyhole + Lid



Hood Lining



Parking Brake Performance



Service Brake Performance Rear Axle





CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT


Report No: 2016221837

DATE
09/01/2024

Water level



Headlight Left



Headlight Right



Boot Lid / Hatch door



Spare Tyre



Door Front Right

**CONDITION REPORT**

Report No: 2016221837

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Door Rear Right



Rear Fender Right



Tyre Rear Right



Rocker Panel Left



Rear Fender Left



Door Rear Left

**CONDITION REPORT**

Report No: 2016221837

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Door Front Left



Front Fender Left



Rocker Panel Right



Belly plates



Belly plates



Rim Front Right





CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Sub Frame



Radiator Cradle



Chassis



Chassis



Chassis



Chassis

**CONDITION REPORT**

Report No: 2016221837

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

Mounting Rubber(s) Rear Axle Left



Belly plates



Belly plates



Engine Wiring



Roof



Hoses



CONDITION REPORT

Report No: 2016221837

DATE
09/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za